

NS/INC21010517/T1tc

ASS. REC. BY: Tan JiaREF: INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. **MT/1148588-001**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: Ms LohVeh No: SHD 4314C Yr Regn: 2019, Nov.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i30 c.c. 1580Colour Blue A/C: Insured / Std / NI / NASp. Reading 240721 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH C85/CV L4 189744Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / SRM / STD A/Rim or

Tyre Size: F: 195/65R15R: 7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 11/10/21Survey held at Comfort LodgeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

**PART BY PART \$1220.10, 2DAYS****RED:906.74;42%**

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L&amp;L: \_\_\_\_\_

Days Of Repair: **2**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHD4314C

Make : HYUNDAI

Model : IONIQ (G3)

Date: 11/10/21

Insurance: NTUC

MVA: MS. LOKE YY

P/P

| Qty | Parts Description / Labour        | Type    | Unit Price | Amount            |
|-----|-----------------------------------|---------|------------|-------------------|
| 1   | REAR BUMPER COVER                 |         |            | Rx \$459.40       |
| 10  | REAR BUMPER CLIPS                 |         |            | uq \$22.00        |
| 1   | REAR BUMPER CENTRE MOULDING ASSY  |         |            | ole \$451.25      |
| 1   | REAR BUMPER REINFORCEMENT         |         |            | ? \$394.80        |
| 1   | REAR BUMPER LOWER CTR MOULDING    |         |            | xR \$155.00       |
| 1   | ANTENNA SMARTKEY                  |         |            | ? \$40.50         |
| 1   | REAR BUMPER FOG LAMP              |         |            | ? \$201.50        |
| 1   | LICENCE LAMP                      |         |            | x \$85.30         |
|     | <b>SUB TOTAL</b>                  |         |            | \$1,482.45        |
|     | <b>LESS 25%</b>                   |         |            | \$370.61          |
|     | <b>DISCOUNTED TOTAL</b>           |         |            | <b>\$1,111.84</b> |
| 1   | REAR BUMPER RUBBER MAT            |         |            | x \$50.00         |
| 1   | REAR NUMBER PLATE WITH TRIM COVER | -10.00% |            | an \$55.00        |
| 1   | REAR BUMPER REVERSE SENSOR        | -10.00% |            | mr \$180.00       |
|     |                                   |         |            | <b>\$235.00</b>   |
|     | <b>Labour Charge</b>              |         |            |                   |
|     | PANEL BEATING                     |         |            | 250 \$400.00      |
|     | SPRAY PAINTING CHARGE             |         |            | 250 \$300.00      |
|     | REMOVE/REFIX REVERSE SENSOR       |         |            | 30 \$80.00        |
|     | <b>TOTAL LABOUR</b>               |         |            | <b>\$780.00</b>   |
|     | <b>ESTIMATE TOTAL</b>             |         |            | <b>\$2,126.84</b> |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495743  
WP' 4/10/21 @ 435

P/P Resurvey new parts

2 days

Tanpin 97495743

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4128342

JC NO305490272

OMER

S COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)

UNIT CARD NO.

REGN NO:

SHD4314C

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 11.10.2021 12:45

YR OF MANU.

14.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU189744

COMPLETION DATE/TIME:


JOB DESCRIPTION

cident Date: 09.10.2021  
TURE: 3P 09.10.2021

NO

LABOR CODE

DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

adgement Slip

Exit Pass

lo.: SHD4314C

YY

Vehicle No.:

SHD4314C

Service Advisor

Signature/Date

Name of Service Advisor

Date