NS/INC21010517/T1tc

ASSIGNMENT SHD 43/4C. Yr Regn: 2019, NOV. From: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Estimated Cost: OD (TP/WS/TP RES / OD RES / EVA / INV / MV Truck / Trailer or Hyundy long. To Inspect Vehicle No: Máka: at Workshop m/s Colour T/Radlo; Insured / Std / NI / NA Sp.Reading Eng/No: Insured: C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake; Inforder / Jammed / Leaked / Burnt or (Client's Record) Modl: NII / SRIM / STD A/Rim o Make of Veh: Tyre Size: (Policy Condition) BS | DUN | EXNOVA | GY | FS | LIZA | MIC | OHTSU | PIR | SUMI | NIS 0/8 Remark: The veh had commenced Its Westfall. TOYO / YOKO or repair at the time of inspection. Rear Front Bal. or Market Value: R/Bal. Consistent? : Yes or No IDAC Accident Rport: ∐Bal. mm 1 /Bal. Consistent?: Yes or No mm GIA / PR Seen: D.O.I. D.O.A. Res.: Yes or No days Est. Repairs: Survey held at 3 Val.: Yes or No Lum Sum: Des. of Damages: Frt / Rear / CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Action / Instruction Date / Time PART BY PART \$1220.10, 2DAYS Days Of Repair: Date/Time, File Pass to? : Prell. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? 8 + RS.__SI Add Fee: : Site Insp (\$: Interview (\$ Photos : Tech. Invs (\$ Others Repersormal: : Weellend (\$ Lump Sum / LEA CF

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD4314C

Make

: HYUNDAI

Model : IONIQ (G3) Date: 11/10/21

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description /	Labour	Туре	Unit Price	Amount
	1 REAR BUMPER COVER				RY\$459.40
1	0 REAR BUMPER CLIPS				wy \$22.00
	1 REAR BUMPER CENTRE MOULDING	ASSY			de \$451.25
	1 REAR BUMPER REINFORCEMENT				\$394.80
	1 REAR BUMPER LOWER CTR MOULD	ING			XK \$155.00
	1 ANTENNA SMARTKEY				? \$40.50
	1 REAR BUMPER FOG LAMP				? \$201.50
	1 LICENCE LAMP				\$85.30
		SUB TOTAL			\$1,482.45
		LESS 25%	1 1		\$370.61
		DISCOUNTED TOTAL	l 1		\$1,111.84
					V 1,111.01
	1 REAR BUMPER RUBBER MAT				× \$50.00
	1 REAR NUMBER PLATE WITH TRIM CO	OVER	-10.00%		\$55.00
	1 REAR BUMPER REVERSE SENSOR		-10.00%		m \$180.00
					\$235.00
	Labour Charge				200
	PANEL BEATING				35 \$400.00
	SPRAY PAINTING CHARGE				25 \$300.00
	REMOVE/REFIX REVERSE SENSOR				3 > \$80.00
		TOTAL LABOUR			\$780.00
		ESTIMATE TOTAL			\$2,126.84
		20			Ψ <u>2,120.04</u>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tayfin 97495749

WP 4 [10] 21 (45)

Plesum new part)

2 days

LKK Auto Consultants hence notic the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey before are subject to confirmation

LKK Auto Consultants hence notify

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 5/9701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 5/5717

Date/Time: 11.10.2021 15:17

Page : 1

JOB CARD Sales Order: 4128342 am: ARC Repair TP(CLSO)1 JC NO305490272 REGN NO.: SHD4314C OMER MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE **FUEL** HYUNDAI 7010045 OMER NO. 383 SIN MING DRIVE E.....1/2.. MODEL TONIQ(G3) 11.10.2021 12:45 Singapore SINGAPORE 575717 65508755 (R) (O) YR OF MANU. 14.11.2019 TARGET DATE (P) CHASSIS CODE KMHC851CVLU189744 COMPLETION DATE/TIME: JUNT CARD NO. JOB DESCRIPTION cident Date: 09.10.2021 TURE: 3P 09.10.2021 NO LABOR CODE DESCRIPTION KED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE

Service Advisor

SHD4314C

edgement Slip

Signature/Date

YY

Name of Service Advisor

SHD4314C

Exit Pass

Vehicle No.: