COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4314C

Make

: HYUNDAI

: IONIQ (G3) Model

Date: 11/10/21 Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			RY\$459.40
- 10	REAR BUMPER CLIPS			wy \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY	ľ		de \$451.2
1	REAR BUMPER REINFORCEMENT	ŀ		un Z \$394.8
1	REAR BUMPER LOWER CTR MOULDING			×/ \$155.0
1	ANTENNA SMARTKEY			nn 7 \$40.5
1	REAR BUMPER FOG LAMP			NY X\$201.5
1	LICENCE LAMP	ľ		un £ \$85.3
			¥	76
			473-25	
	SUB TO	TAL ,	10.00	\$1,482.4
	LESS	25% W/.	378.60	\$370.6
	DISCOUNTED TO	TAL		\$1,111.8
4	REAR BUMPER RUBBER MAT		,	40'X \$50.0
	REAR NUMBER PLATE WITH TRIM COVER	-10.00%	235	an \$55.0
	REAR BUMPER REVERSE SENSOR	-10.00%	235	m/\$180.0
		10.0070	101,711.22	\$235.0
				3,200
	Labour Charge			
	PANEL BEATING			\$50 \$400.0
	SPRAY PAINTING CHARGE	į.	630	25 \$300.0
	REMOVE/REFIX REVERSE SENSOR			32 \$80.0
	TOTAL LABO	DUR		\$780.0
	ESTIMATE TO	TAL	\$ 1220.10 Adays	\$2,126.8
			X = *	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taffin 97495749

WP 4 [10]21 C 455

P/P resum none parts

2 days

taffin C Mbanto....

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer