

INC

Veh No: SHD 4314C Yr Regn: 2019 / Nov  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Veh No: SHD 43/4C. Yr Regn: 2019, Nov.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Måke: flyndu'lon/g. C.C 1580.

Colour: Blue A/C: ✓ Insured / Std / NI / NA

Sp. Reading 240711 T/Radlo; Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHC88/CVLY189794

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or/

Tyre Size: F: 195/65/15

R: 7.5.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

RS / DIIN / EYNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Guest House

|       |      |
|-------|------|
| Front | Rear |
|-------|------|

R/Bal. 6 mm R/Bal. 6 mm

1/Bal. 6 mm

D.O.I. 11/20/21

Case last year:

Survey held at Compton Canyon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

          : Prell. Report

☐ : Final Report

□

LUCKY SUM / L.B.H. (F)

Resurvey No. of Trip:

Transportation:

1 Photos

|   |        |  |
|---|--------|--|
| 1 | Others |  |
|---|--------|--|

TOTAL

Add Fee: ☐ : Site Insp (\$)

Interview (\$

1: Tech. Invs (\$

Weekend (5)

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHD4314C

Make : HYUNDAI

Model : IONIQ (G3)

Date: 11/10/21

Insurance: NTUC

MVA: MS. LOKE YY

| Qty | Parts Description / Labour        | Type    | Unit Price | Amount            |
|-----|-----------------------------------|---------|------------|-------------------|
| 1   | REAR BUMPER COVER                 |         |            | Rx \$459.40       |
| 10  | REAR BUMPER CLIPS                 |         |            | uq \$22.00        |
| 1   | REAR BUMPER CENTRE MOULDING ASSY  |         |            | ole \$451.25      |
| 1   | REAR BUMPER REINFORCEMENT         |         |            | ? \$394.80        |
| 1   | REAR BUMPER LOWER CTR MOULDING    |         |            | xR \$155.00       |
| 1   | ANTENNA SMARTKEY                  |         |            | ? \$40.50         |
| 1   | REAR BUMPER FOG LAMP              |         |            | ? \$201.50        |
| 1   | LICENCE LAMP                      |         |            | x \$85.30         |
|     | <b>SUB TOTAL</b>                  |         |            | \$1,482.45        |
|     | <b>LESS 25%</b>                   |         |            | \$370.61          |
|     | <b>DISCOUNTED TOTAL</b>           |         |            | <b>\$1,111.84</b> |
| 1   | REAR BUMPER RUBBER MAT            |         |            | x \$50.00         |
| 1   | REAR NUMBER PLATE WITH TRIM COVER | -10.00% |            | an \$55.00        |
| 1   | REAR BUMPER REVERSE SENSOR        | -10.00% |            | mr \$180.00       |
|     |                                   |         |            | <b>\$235.00</b>   |
|     | <b>Labour Charge</b>              |         |            |                   |
|     | PANEL BEATING                     |         |            | 250 \$400.00      |
|     | SPRAY PAINTING CHARGE             |         |            | 250 \$300.00      |
|     | REMOVE/REFIX REVERSE SENSOR       |         |            | 30 \$80.00        |
|     | <b>TOTAL LABOUR</b>               |         |            | <b>\$780.00</b>   |
|     | <b>ESTIMATE TOTAL</b>             |         |            | <b>\$2,126.84</b> |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495743  
WP' 4/10/21 @ 435

P/P Resurvey new parts

2 days

Tanpin 97495743

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4128342

JC NO305490272

OMER

S COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)

UNIT CARD NO.

REGN NO:

SHD4314C

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 11.10.2021 12:45

YR OF MANU.

14.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU189744

COMPLETION DATE/TIME:


JOB DESCRIPTION

cident Date: 09.10.2021  
TURE: 3P 09.10.2021

NO

LABOR CODE

DESCRIPTION



VED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHD4314C

YY

Vehicle No.:

SHD4314C

Service Advisor

Signature/Date

Name of Service Advisor

Date