



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1007A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CUT	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER STAY RH	SERVICEABLE	138.10	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR UNDER CENTRE COVER	TO REPAIR SEE LABOUR	225.00	-
1	BOOTLID COVER	DEFORMED	2,480.40	2,480.40
1	BOOTLID H EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID EMBLEM IONIQ	NECESSARY	31.80	31.80
1	BOOTLID EMBLEM HYBRID	NECESSARY	24.30	24.30
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR SMART KEY SENSOR	CUT	40.50	40.50
2	REAR BUMPER BRACKET LH/RH @\$55.80	SERVICEABLE	111.60	-
	LESS 20% DISCOUNT		-903.19	-709.53
			3,612.76	2,838.12
<b><u>SPECIAL NETT ITEMS</u></b>				
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	40.00	40.00
2	BOOTLID COMFORT/TEL NUMBER STICKER @\$30.00 (SN)	NECESSARY	60.00	60.00
1	BOOT LID ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR NUMBER PLATE W/HOLDER (SN)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (SN)	CUT	180.00	180.00
			435.00	435.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR UNDER CENTRE COVER.		850.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING AND LIGHTING.		60.00	20.00
	REMOVE/REFIX REAR W/SCREEN (BIG & SMALL).		120.00	120.00

Report Ref No. NS/INC21010521/Vqcn2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		90.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			1,780.00	1,390.00
GRAND TOTAL			5,827.76	4,663.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,700.00

Report Ref No. NS/INC21010521/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.