

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010524/ATY3N2**Date:** 20/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00170452000		
<b>Claimant Vehicle No :</b>	SLZ5444R	<b>Insured Vehicle No :</b>	SDU11K		
Date of Loss:	10/10/2021	Nature of Claim:	TP	Claim No:	SNM21D205778/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLZ5444R</b>		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520456439
Reg. Date:	08/05/2018 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0164600
Colour:	Silver	Odometer:	105608 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,940.48	1,800.80	3,139.68	63.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,255.00	1,030.00	1,225.00	54.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,195.48</b>	<b>2,830.80</b>	<b>4,364.68</b>	<b>60.66</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,200.00</b>		
<b>(\$\$)</b>	7,195.48	2,200.00	4,995.48	69.43
<b>+ GST 7.00/7.00% (\$\$)</b>	503.68	154.00	349.68	69.43
<b>Nett Amount (\$\$)</b>	<b>7,699.16</b>	<b>2,354.00</b>	<b>5,345.16</b>	<b>69.43</b>

**INSPECTION**

Date of Assignment:	13/10/2021	
Date Inspected:	13/10/2021 Inspected At:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2021)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ5444R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,004.00 FL	*- FL
2	1		*REAR BOOT LID LOGO EMBLEM	Necessary	58.90 FL	*58.90 FL
3	1		*REAR BOOT LID MAZDA 3 EMBLEM	Necessary	56.40 FL	*56.40 FL
4	1		*REAR BOOT LID SKYACTIV TECHNOLOGY EMBLEM	Necessary	67.90 FL	*67.90 FL
5	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	187.90 FL	*- FL
6	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	114.80 FL	*- FL
7	2		*REAR BOOT LID RUBBER GUIDE STOPPER	Not Necessary	23.00 FL	*- FL
8	2		*REAR TAILLAMP LH/RH	Not Necessary	1,068.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,127.00 FL	*1,127.00 FL
10	2		*REAR BUMPER TOW HOOK COVER LH/RH	Not Necessary	59.60 FL	*- FL
11	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	169.20 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER LH/RH	Necessary	77.40 FL	*77.40 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	563.00 FL	*563.00 FL
14	2		*REAR BUMPER INNER SIDE SHIELD LH/RH	Not Necessary	168.40 FL	*- FL
15	1		*REAR BUMPER CENTER RETAINER	Cracked	12.90 FL	*12.90 FL
16	1		*REAR END PANEL	Repair	530.00 FL	*- FL
17	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	99.70 FL	*- FL
18	1		*SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS	Not Necessary	50.00 FS	*- FS
19	2		*REAR TAILLAMP CLIPS SET LH/RH	Not Necessary	80.00 FS	*- FS
20	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
21	1		*SET REAR BUMPER REVERSE SENSOR	Bent	280.00 FS	*200.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,018.10</b>	<b>2,193.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,077.62	392.70
<b>Total Parts (\$\$)</b>	<b>4,940.48</b>	<b>1,800.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	800.00	300.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	800.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	85.00	50.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO PERFORM & TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	New	150.00	0.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
7	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	180.00	0.00
8	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,255.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >