

ASS. REG. BY:

REF:

Smo/21010525/Kg f3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

CMTD2103050/RUC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

03/2024

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1/ GIA not ready

15/10/21 @ 2.44pm revised to Ruth Chua by email.

Kenneth confirmed LS \$3300, 6 days (Red \$3767.50, 53%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 11/11 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum H.D.T. (\$

3300

AUTOLUTION
CARTIMES
CarTimes Autolution Pte Ltd
160 Sin Ming Drive AutoCity
#02-04 Singapore 575722
Tel : 6471 5111
Email : claims@cartimes.com.sg

Not Authorized
11/12/12
Running After Policy
6 days

VEHICLE NO: GX5996J

MODEL: TOYOTA LITEACE

CHASSIS NO: CR42-5009310

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
TAILGATE		\$ ^{As} 800.00 ✓
TAILGATE INNER BOARD		\$ ⁱⁿ 200.00 X
REAR BUMPER		^{Bu} \$ 400.00 ✓
REAR BUMPER RETAINER RHS		\$ ^{CM} 100.00 ✓
REAR FENDER RHS		^{As} \$ 1,200.00 ✓
REAR FENDER INNER SHIELD		ⁱⁿ \$ 180.00 X
REAR FENDER RAILING RHS		\$ ^{2h} 300.00 X
REAR FENDER INNER TRIM RHS		\$ ⁱⁿ 400.00 X
REAR WINDSCREEN		^{Shower} \$ 600.00 ✓
REAR WINDSCREEN MOULDING		\$ ⁱⁿ 80.00 ✓
TAIL LAMP RHS		^{Bu} \$ 250.00 ✓
END PANEL		^R \$ 300.00 X
END PANEL TOP GARNISH		ⁱⁿ \$ 200.00 X
	25%	\$ 5,010.00
		\$ 1,252.50
		\$ 3,757.50
<u>SPECIAL NETT ITEMS</u>		
REAR BUMPER CLIPS 1 SET		ⁱⁿ \$ 60.00 ✓
	Total	\$ 60.00
TOTAL PARTS		\$ 3,817.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,500.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,200.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ 100.00
5	Remove & refit rear windscreen	\$ 200.00
6	Transfer tailgate parts	\$ 150.00
	Labour Total :	\$ 3,250.00
	TOTAL (PARTS & LABOUR):	\$ 7,067.50

7001

7001

201

601

1201

601