



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 5996J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAIL GATE	BENT	800.00	800.00
1	TAILGATE INNER BOARD	SERVICEABLE	200.00	-
1	REAR BUMPER	BUCKLED	400.00	371.55
1	REAR BUMPER RETAINER RHS	CRACKED	100.00	100.00
1	REAR FENDER RHS	BENT	1,200.00	1,018.30
1	REAR FENDER INNER SHIELD	SERVICEABLE	180.00	-
1	REAR FENDER RAILING RHS	SERVICEABLE	300.00	-
1	REAR FENDER INNER TRIM RHS	SERVICEABLE	400.00	-
1	REAR WINDSCREEN	SHATTERED	600.00	600.00
1	REAR WINDSCREEN MOULDING	NECESSARY	80.00	80.00
1	TAIL LAMP RHS	BROKEN	250.00	250.00
1	END PANEL	TO REPAIR SEE LABOUR	300.00	-
1	END PANEL TOP GARNISH	SERVICEABLE	200.00	-
	LESS 25% DISCOUNT		-1,252.50	-804.96
			3,757.50	2,414.89
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
			60.00	60.00
	<b><u>LABOUR</u></b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS & TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,500.00	700.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,200.00	700.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	20.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		100.00	60.00
	REMOVE & REFIT REAR WINDSCREEN.		200.00	120.00

Report Ref No. CS/SMO21010525/Kqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER TAILGATE PARTS.		150.00	60.00
			3,250.00	1,660.00
GRAND TOTAL			7,067.50	4,134.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS/SMO21010525/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.