

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010526/KVY3N2**Date:** 28/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00081442100

Claimant Vehicle No : SKU5620L **Insured Vehicle No :** SMX1533S

Date of Loss: 11/10/2021 Nature of Claim: TP Claim No: SNM21D205809/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU5620L**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX521035

Reg. Date: 31/07/2015 (Man. Year: 2015) Chassis No: MR053REH104535735

Colour: Metallic Silver Odometer: 164378 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,541.57	1,385.80	2,155.77	60.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,360.00	1,310.00	49.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,211.57	2,745.80	3,465.77	55.80
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	6,211.57	2,200.00	4,011.57	64.58

INSPECTION

Date of Assignment: 13/10/2021

Date Inspected: 13/10/2021 Inspected At: Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU5620L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	710.10 FL	*- FL
2	2		*REAR BOOT LID HINGES	Repair	362.60 FL	*- FL
3	1		*REAR BOOT LID UPPER LOCK	Dented	89.30 FL	*89.30 FL
4	1		*REAR BOOT LID LOWER LOCK	Distorted	89.30 FL	*89.30 FL
5	1		*REAR EMBLEM LOGO TOYOTA	Necessary	57.90 FL	*57.90 FL
6	1		*REAR EMBLEM TOYOTA IN WORDING	Necessary	35.30 FL	*35.30 FL
7	1		*REAR EMBLEM ALTIS	Necessary	40.20 FL	*40.20 FL
8	1		*REAR TAILEND PANEL	Bent	301.70 FL	*301.70 FL
9	1		*REAR TAILEND TOP GARNISH	Mtg Distorted	121.20 FL	*121.20 FL
10	1		*REAR BUMPER	Buckled	354.70 FL	*354.70 FL
11	1		*REAR BUMPER BEAM	Bent	401.90 FL	*380.00 FL
12	2		*REAR BUMPER BRACKET	Repair	226.80 FL	*- FL
13	2		*REAR BUMPER RETAINER	Serviceable	113.40 FL	*- FL
14	5		*REAR BUMPER FASTENER	Serviceable	40.00 FL	*- FL
15	5		*REAR BUMPER EXTENSION GROMMET SCREW	Serviceable	40.00 FL	*- FL
16	5		*REAR BUMPER EXTENSION GROMMET SCREW	Serviceable	40.00 FL	*- FL
17	1		*REAR SILENCER	Repair	1,124.90 FL	*- FL
18	1		*REAR TAILEND PANEL TEROSTAT SEALANT	Necessary	54.20 FS	*30.00 FS
19	1		*REAR BOOT LID WEATHERSTRIP (50%)	Cut	80.40 FS	*53.60 FS
20	1		*REAR NO PLATE (SMOOTH)	Serviceable	25.00 FS	*- FS
21	1		*REAR NO PLATE HOLDER	Serviceable	20.00 FS	*- FS
22	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,578.90	1,753.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,037.33	367.40
Total Parts (\$\$)	3,541.57	1,385.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	120.00	30.00
2	TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID	New	80.00	0.00
3	TO CHECK WATER SEEPAGE	New	60.00	20.00
4	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	New	60.00	50.00
5	TO REPAIR,REPLACE ON REAR AFFECTED SILENCER	New	150.00	0.00
6	TO CUT & WELD ON REPLACED PANEL,TO STRAIGHTEN,RE-ALIGN ON REAR AFFECTED & LABOUR TO REPLACE ABOVE PARTS	New	1,000.00	600.00
7	TO PUTTY,PRIMER & SPRAY PAINT ON REAR AFFECTED BOOT LID,REAR END PANEL,BEAM,BUMPER & SENSOR USING 2K PAINT	New	1,200.00	660.00
Gross Labour Cost (\$)			2,670.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >