

Taiping



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Repair Estimates

SLJ 7990 B

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>4,886.70</u>
	Plus/Less 20%	\$	<u>977.34</u>
	<b>Total of Cost / List</b>	\$	<u><u>3,909.36</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items	\$	<u>105.00</u>
	<b>Total Parts Cost</b>	\$	<u><u>4,014.36</u></u>
	<b>Labour</b>	\$	<u><u>1,650.00</u></u>
	<b>Total</b>	\$	<u><u>5,664.36</u></u>

*Not authorized  
LI Rep @ 3050/hr  
Pickup After Paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 13/10/21 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Pe Date: 13/10/21



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

### Spare Parts

Vehicle No. : SLJ 7990 B

Make & Model : HONDA VEZEL

Chassis No : RU31217164

Submit By : serence

Year Manufacture : 27-Dec-16

Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front grille <i>351.80 mfg cost</i>	1	\$391.80		<input checked="" type="checkbox"/>
2	Front grille chrome <i>421 CMJ</i>	1	\$445.00		<input checked="" type="checkbox"/>
3	Front grille emblem <i>non</i>	1	\$33.40		<input type="checkbox"/>
4	Headlamp LH <i>cost</i>	1	\$1,850.00		<input type="checkbox"/>
5	Headlamp lower bracket LH <i>R</i>	1	\$38.00		<input checked="" type="checkbox"/>
6	Headlamp upper bracket LH <i>Sn</i>	1	\$29.60		<input checked="" type="checkbox"/>
7	Front bumper <i>762.70 CMJ</i>	1	\$881.70		<input type="checkbox"/>
8	Front bumper clip <i>non</i>	10	\$35.00	S.N	<input type="checkbox"/>
9	Front bumper reinforcement <i>R</i>	1	\$351.00		<input checked="" type="checkbox"/>
10	Front bumper side retainer LH <i>brs</i>	1	\$27.50		<input checked="" type="checkbox"/>
11	Front bumper side retainer RH <i>R</i>	1	\$27.50		<input checked="" type="checkbox"/>
12	Front bumper bracket LH <i>R</i>	1	\$29.60		<input checked="" type="checkbox"/>
13	Front bumper bracket RH <i>R</i>	1	\$29.60		<input checked="" type="checkbox"/>
14	Fog lamp LH <i>Sn</i>	1	\$357.00		<input checked="" type="checkbox"/>
15	Fog lamp garnish LH <i>Ru</i>	1	\$45.00		<input type="checkbox"/>
16	LH front fender undershield <i>Sn</i>	1	\$155.00		<input checked="" type="checkbox"/>
17	LH front fender undershield clip <i>non</i>	10	\$35.00	S.N	<input checked="" type="checkbox"/>
18	LH front fender protector <i>Bu</i>	1	\$195.00		<input type="checkbox"/>
19	LH front fender protector clip <i>non</i>	10	\$35.00	S.N	<input type="checkbox"/>
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

