11/23/21, 4:06 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21010529/KUF3N2

23/11/2021 Date:

REFERENCE

Claimant Vehicle

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

SHF595Z Insured Vehicle No: XD5613T No:

Date of Loss: 11/10/2021 Nature of Claim: TP Claim No: CDMFG21001983

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF595Z

TOYOTA PRIUS, 1.5 (A) Make & Model: Engine No: 2ZR2H07829

Reg. Date: 30/10/2020 (Man. Year: 2020) Chassis No: JTDKB3FU803092407

Colour: Metallic Pearl White/Red Odometer: 65015 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Rear Tyre Size: Front Tyre Size: 195/65R15 195/65R15 Front Left Side: Rear Left Side: Sailun 9 mm Dunlop 4 mm Front Right Side: Sailun 9 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		33,454.82	7,892.05	25,562.77	76.41
Miscellaneous Items		0.00	0.00	0.00	
Labour		10,290.00	3,350.00	6,940.00	67.44
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	43,744.82	11,242.05	32,502.77	74.30
	+ GST 7.00/7.00% (S\$)	3,062.14	786.94	2,275.20	74.30
	Nett Amount (S\$)	46,806.96	12,028.99	34,777.97	74.30

INSPECTION

Date of Assignment: 13/10/2021

Trans-Cab Services Pte Ltd (HQ) Date Inspected: 13/10/2021 Inspected At:

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11/23/21, 4:06 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF595Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Repair	332.70 FL	*-FL
3	1		*COCER,REAR BUMPER LOWER	Missing	22.00 FL	*22.00 FL
4	1		*GUARD REAR BUMPER CENTER	Mtg Cracked	374.50 FL	*374.50 FL
5	1		*RETAINER,REAR BUMPER SIDE,RH	Cracked	132.60 FL	*132.60 FL
6	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	*-FL
7	1		*LAMP ASSY,REAR RH	Cracked	293.60 FL	*293.60 FL
8	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME NO 2	Not Necessary	54.60 FL	*-FL
9	1		*PLATE,BACK DOOR NAME NO 1	Not Necessary	54.60 FL	*-FL
10	1		*ORNAMENT SUB-ASSY,BACK DOOR	Not Necessary	47.90 FL	*-FL
11	1		*GARNISH SUB-ASSY,BACK DOOR OUTSIDE	Serviceable	913.60 FL	*-FL
12	1		*WEATHERSTRIP BACK DOOR	Serviceable	372.30 FL	*-FL
13	1		*PANEL ASSY,DECK TRIM SIDE RH	Serviceable	355.90 FL	*- FL
14	1		*COVER,FLOOR UNDER NO 2 RH	Serviceable	241.90 FL	*-FL
15	1		*COVER REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
16	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	*-FL
17	1		*PANEL SUB-ASSY,BODY,QUARTER RH	Bent	871.50 FL	*871.50 FL
18	1		*LINER REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	*-FL
19	1		*DUCT ASSY,QUARTER VENT,RH	Dented	67.00 FL	*67.00 FL
20	1		*MOULDING ASSY,BODY ROCKER PANEL,RH	Serviceable	594.80 FL	*-FL
21	1		*EMBLEM SIDE PANEL	Serviceable	54.60 FL	*- FL
22	1		*LINER,FRONT FENDER,RH	Serviceable	202.50 FL	*- FL
23	1		*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	*977.80 FL
24	1		*MIRROR ASSY,OUTER REAR VIEW RH	Serviceable	1,436.60 FL	*- FL
25	1		*COVER SUB-ASSY,FRONT PILLAR,UPR RH	Serviceable	100.40 FL	*-FL
26	1		*PANEL SUB-ASSY,FRONT DOOR,RH	Repair	1,300.70 FL	*- FL
27	1		*LOCK ASSY,FRONT DOOR W/MOTOR,RH	Repair	603.20 FL	*-FL
28	1		*MOULDING,FRONT DOOR WINDOW FRAME,FRONT RH	Serviceable	38.60 FL	*- FL
29	1		*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	*-FL
30	1		*HANDLE ASSY,FRONT DOOR OUTSIDE RH	Serviceable	390.60 FL	*- FL
31	1		*MOTOR ASSY,POWER WINDOW REGULATOR,RH	Serviceable	926.00 FL	*- FL
32	1		*WEATHERSTRIP,FRONT DOOR OPENING TRIM,RH	Serviceable	321.10 FL	*- FL
33	1		*HINGE ASSY,FRONT DOOR,LOWER RH	Repair	110.60 FL	*-FL
34	1		*HINGE ASSY,FRONT DOOR,UPPER RH	Repair	97.50 FL	*- FL
35	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW RH	Repair	238.30 FL	*- FL
36	1		*TAPE,BLACK OUT,NO 2 FRT RH	Not Necessary	43.50 FL	*- FL
37	1		*TAPE,BLACK OUT,NO 1 FRT RH	Not Necessary	13.30 FL	*- FL
38	1		*TAPE,BLACK OUT,NO 3 FRT RH	Not Necessary	26.30 FL	*- FL
39	1		*PANEL SUB-ASSY,REAR DOOR,RH	Repair	1,294.90 FL	*-FL
40	1		*FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	*-FL
41	1		*HANDLE ASSY,REAR DOR OUTSIDE RH	Serviceable	97.40 FL	*-FL
42	1		*WEATHERSTRIP,REAR DOOR OPENING TRIM,RH	Serviceable	293.00 FL	*-FL
43	1		*MOTOR ASSY,POWER WINDOW REGULATOR,REAR RH	Serviceable	926.00 FL	*-FL
44	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW RH	Serviceable	206.70 FL	*- FL
45	1		*TAPE BLACK OUT,NO 2 REAR RH	Not Necessary	34.90 FL	*-FL
	1		*TAPE BLACK OUT,NO 3 REAR RH	Not Necessary	15.40 FL	*- FL

11/23/21, 4:06 PM Adjuster Report

lo.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
17	1		*TAPE BLACK OUT,NO 1 REAR RH		Not Necessary	21.90 FL	*- FL
-8	1		*HINGE ASSY,REAR DOOR LOWER RH		Repair	87.10 FL	*- FL
9	1		*HINGE ASSY,REAR DOOR UPPER RH		Repair	98.90 FL	*- Fl
0	1		*COVER,FRONT BUMPER		Bent	521.00 FL	*521.00 FL
1	1		*MOULDING,FRONT BUMPER SIDE,RH		Cracked	95.60 FL	*95.60 FL
2	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTI	NG	Bent	110.50 FL	*110.50 FI
3	1		*RIM		Serviceable	1,900.10 FL	*- FI
4	1		*WIRE,ENGINE ROOM MAIN		Serviceable	7,323.90 FL	*- FI
5	1		*EXTENSION,FRONT BUMPER RH		Repair	120.10 FL	*- FI
6	1		*COVER SUB-ASSY ENGINE UNDER,NO 2		Serviceable	241.90 FL	*- FI
7	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER		Bent	716.60 FL	*716.60 FI
8	1		*REINFORCEMENT,FRONT BUMPER,NO 2		Bent	246.10 FL	*246.10 F
9	1		*ABSORBER,FRONT BUMPER ENERGY		Cracked	80.20 FL	*80.20 FI
0	1		*ABSORBER,FRONT BUMPER,LOWER		Cracked	132.70 FL	*132.70 F
61	1		*SUPPORT,FRONT BUMPER SIDE,RH		Bent	80.10 FL	*80.10 Fl
32	1		*JAR ASSY,WINDSHIELD WASHER		Dented	219.10 FL	*219.10 FL
3	1		*COVER,FRONT BUMPER HOLE LH		Missing	30.20 FL	*30.20 FI
4	1		*COVER,FRONT BUMPER HOLE RH		Missing	30.20 FL	*30.20 FI
5	1		*GRILLE SUB-ASSY,RADIATOR		Cracked	422.50 FL	*422.50 FI
6	1		*GRILLE RADIATOR,LOWER NO 1		Missing	178.60 FL	*178.60 FI
7	1		*EMBLEM ASSY,RADIATOR GRILLE		Missing	105.80 FL	*105.80 FI
8	1		*LAMP ASSY,FOG,LH		Serviceable	237.10 FL	*- FI
9	1		*LAMP ASSY,FOG,RH		Missing	237.10 FL	*237.10 FI
0	1		*UNIT ASSY,HEADLAMP RH		Cracked	2,637.60 FL	*2,637.60 FI
'1	1		*HOOD SUB-ASSY		Bent	983.10 FL	*983.10 FI
2	1		*LOCK ASSY,HOOD		Repair	135.00 FL	*- Fl
3	1		*HINGE ASSY,HOOD,LH		Bent	58.90 FL	*58.90 FI
4	1		*HINGE ASSY,HOOD,RH		Bent	58.90 FL	*58.90 FI
'5	1		*HOSE,AIR CLEANER NO 1		Serviceable	74.00 FL	*- FI
6	1		*INLET,AIR CLEANER NO 2		Serviceable	112.70 FL	*- FL
7	1		*CLEANER ASSY,AIR		Serviceable	1,147.00 FL	*- FI
8	1		*CASE SUB-ASSY,AIR CLEANER		Serviceable	228.80 FL	*- Fl
'9	1		*CONDENSER ASSY,COOLER		Serviceable	1,783.20 FL	*- FI
0	1		*SUPPORT SUB-ASSY,RADIATOR LH		Serviceable	245.10 FL	*- Fl
31	1		*SUPPORT SUB-ASSY, RADIATOR RH		Serviceable	245.10 FL	*- FI
32	1		*SET PARKING AID		Serviceable	700.00 FS	*- FS
3	1		*SET REAR BUMPER CLIP		Necessary	95.00 FS	*50.00 F
	2		*WINDSCREEN SEALANT		Not Necessary	150.00 FS	*- F
35	1		*WINDSCREEN MOULDING		Not Necessary	200.00 FS	*- F
6	1		*WINDSCREEN INNER SPONGE SEAL		Not Necessary	130.00 FS	*- F
37	1		*REAR RH FENDER LINER CLIP		Not Necessary	65.00 FS	*-F
8	1		*FRT RH FENDER LINER CLIP		Not Necessary	65.00 FS	*- FS
9	1		*REAR TAILGATE STICKER TRANS-CAB		Not Necessary	80.00 FS	*- F
0	1		*REAR TAILGATE STICKER 6555-3333		Not Necessary	80.00 FS	*- F
1	1		*RIM		Serviceable	1,879.40 FS	*- F
92	1		*DOOR STICKER TRANSCAB		Necessary	100.00 FS	*60.00 F
3	1		*DOOR STICKER TEL NO		Necessary	100.00 FS	*60.00 F
4	1		*DOOR TRIM CLIP		Not Necessary	75.00 FS	*- F
5	1		*DOOR WEATHERSTRIP CLIP		Not Necessary	80.00 FS	*- F:
6	1		*REAR BUMPER PROTECTOR		Serviceable	180.00 FS	*- F
7	1		*REAR BUMPER RETAINER CLIP			85.00 FS	*- F
<i>1</i> 8	1		*END PANEL TRIM CLIP		Not Necessary		*- F
-					Not Necessary	65.00 FS	
9	1		*SET BUMPER CLIP FRT *EPONT NUMBER DI ATE WITH MOULDING		Necessary	95.00 FS	*50.00 FS
	1		*FRONT NUMBER PLATE WITH MOULDING		Missing	200.00 FS	*45.00 F
	1		*SET FRNT BUMPER RETAINER CLIP		Not Necessary	85.00 FS	*- FS
02	1		*COVER DECK TRIM,REAR		Serviceable	126.70 FL	*- FL

 Sub Total (S\$)
 43,103.30
 10,434.40

 - List Item Discount on L Items 25.00/25.00% (S\$)
 9,648.48
 2,542.35

Report was unsubmitted during this print-out.

No. Qty Part No. Particulars	Condition	Repairer's	Amount
	Total Parts (S\$)	33,454.82	7,892.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	100.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	1,200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING, BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	90.00
12	TOWING FEES	New	150.00	50.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	1,760.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
	Gross Labour	Cost (S\$)	10,290.00	3,350.00
	Report was unsubmitted during this p	orint-out		
	report was unsubmitted during time p	Jinit-Out.		

< END OF ESTIMATES >