

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21010531/EVF3E2  
**Date:** 21/10/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210076695  
**Claimant Vehicle No :** FBS1028R **Insured Vehicle No :** GBK8055H  
Date of Loss: 05/10/2021 Nature of Claim: TP Claim No: 3279985954SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS1028R**  
Make & Model: HONDA CB150R, 149cc Engine No: KC32E0036349  
Reg. Date: 23/01/2021 (Man. Year: 2020) Chassis No: MLHKC2886K5136349  
Colour: Red Odometer: 10712 km  
Engine Capacity: 149 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 140/70 R17  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 13/10/2021  
Date Inspected: 13/10/2021 Inspected At: Speedway Motor Pte Ltd (Toh Guan)  
No. 36 Toh Guan Road East #01-32 Enterprise Hub  
Singapore 608580  
Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$12,000.00 (EST)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	2		*FRONT WING MIRROR	Cut	0.00 F	*- F
3	1		*ERP UNIT	Cut	0.00 F	*- F
4	1		*STEERING CONE	Necessary	0.00 F	*- F
5	1		*HANDLE BAR	Bent	0.00 F	*- F
6	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
7	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
8	2		*FUEL TANK (COVER)	Broken	0.00 F	*- F
9	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
10	2		*REAR FAIRING (LH & RH)	Broken	0.00 F	*- F
11	1		*SEAL ASSY	Torn	0.00 F	*- F
12	2		*ENGINE GUARD MOUNTING	Cut	0.00 F	*- F
13	1		*FOOT BRAKE	Bent	0.00 F	*- F
14	1		*FRONT FOOT REST	Cut	0.00 F	*- F
15	2		*REAR FOOT REST	Missing	0.00 F	*- F
16	2		*REAR FOOT REST BRACKET	Broken	0.00 F	*- F
17	1		*REAR FENDER MUDFLAP	Broken	0.00 F	*- F
18	1		*SWING ARM (REAR)	* Check	0.00 F	*- F
19	1		*REAR LH SIGNAL LAMP	Cut	0.00 F	*- F
20	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
21	1		*REAR BOX	Broken	0.00 F	*- F
22	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
23	1		*EMBLEM	Necessary	0.00 F	*- F
24	1		*STICKER	Necessary	0.00 F	*- F
25	1		*REAR REFLECTOR	Cracked	0.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**

**0.00**

**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**