

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21010532/AQCE2

**Date:** 25/02/2022

### REFERENCE

Insured/Claimant:	LIM GEOK CHOO (LIN YUZHU)	Policy No:	7210036748	
Date of Loss:	12/10/2021	Nature of Claim:	OD	Claim No: 2145911065SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8181J		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DKY015270
Reg. Date:	12/04/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF27MN051947
Colour:	Black	Odometer:	11689 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$225,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,018.00	11,362.72	9,655.28	45.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	3,022.00	2,950.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,990.00</b>	<b>14,384.72</b>	<b>12,605.28</b>	<b>46.70</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>26,390.00</b>	<b>13,784.72</b>	<b>12,605.28</b>	<b>47.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,847.30</b>	<b>964.93</b>	<b>882.37</b>	<b>47.77</b>
<b>Nett Amount (S\$)</b>	<b>28,237.30</b>	<b>14,749.65</b>	<b>13,487.65</b>	<b>47.77</b>

### INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	13/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	650.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	222.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER - RH	Damaged	39.00 FS	*31.20 FS
5	1		*FRONT BUMPER MOUNTING BRACKET - RH	Not Necessary	111.00 FS	*- FS
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	153.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Torn	210.00 FS	*167.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	434.00 FS	*346.80 FS
9	2		*FRONT BUMPER AIR GUIDE - RH	Cracked	58.00 FS	*22.56 FS
10	1		*FRONT RADIATOR GRILLE	Not Necessary	2,217.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	226.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	1,012.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	44.00 FS	*35.12 FS
14	2		*FRONT BUMPER SUPPORT	Not Necessary	59.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET - RH	Not Necessary	54.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Cracked	126.00 FS	*100.40 FS
17	1		*HORN	Not Necessary	216.00 FS	*- FS
18	1		*HORN BRACKET	Not Necessary	47.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
20	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	9.00 FS	*- FS
21	1		*FRONT FENDER - RH	Dented	1,468.00 FS	*1,174.40 FS
22	1		*FRONT FENDER BRACE - RH	Bent	118.00 FS	*94.40 FS
23	1		*FRONT FENDER BRACKET - RH	Not Necessary	44.00 FS	*- FS
24	1		*FRONT FENDER ATTACHEMENT PART	Not Necessary	42.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER - RH	Torn	266.00 FS	*212.80 FS
26	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER - RH	Not Necessary	166.00 FS	*- FS
28	1		*STONE CHIP GUARD - RH	Not Necessary	51.00 FS	*- FS
29	1		*HEADLIGHT MOUNTING - RH	Not Necessary	118.00 FS	*- FS
30	1		*HEADLIGHT - RH	Cut	8,624.00 FS	*6,899.20 FS
31	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	198.00 FS	*- FS
32	1		*HEADLIGHT WASHER HOSE	Not Necessary	182.00 FS	*- FS
33	1		*SET FRONT BUMPER WIRING	Not Necessary	577.00 FS	*- FS
34	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
35	1		*SUNDRIES	Necessary	300.00 FS	*1.76 FS
36	1		*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,018.00 11,362.72

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,972.00</b>	<b>3,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >