

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21010533/T1QF3E2

**Date:** 12/01/2022

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070124391
<b>Claimant Vehicle No :</b>	SBS8667A	<b>Insured Vehicle No :</b>	SDH1616C
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	5529720341SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS8667A</b>	Engine No:	6419386
Make & Model:	SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A)	Chassis No:	YS2K4X20001864535
Reg. Date:	24/06/2009 (Man. Year: 2009)	Odometer:	895976 km
Colour:	Multi-colour		
Engine Capacity:	9290 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	180.00	180.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,134.00	950.00	184.00	16.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,314.00</b>	<b>1,130.00</b>	<b>184.00</b>	<b>14.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	91.98	79.10	12.88	14.00
<b>Nett Amount (S\$)</b>	<b>1,405.98</b>	<b>1,209.10</b>	<b>196.88</b>	<b>14.00</b>

### INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	14/10/2021	Inspected At:	Sbs Transit Ltd ( Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	3.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY	Bent	140.00 F	*140.00 F
2	2		*GAS JACK 0200N;RR ENG DOOR	Bent	40.00 F	*40.00 F
F=Franchise part.						
Total Parts (S\$)					180.00	180.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR COST	New	950.00	950.00
2	WORKSHOP LABOUR COST	New	184.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,134.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >