



Accident Reference & Bus No: **E/4350/2021 – SBS8667A with SDH1616C**

Activated date: **13/10/2021 14:05**

Activated by: Ang Chong Boon <angcb@sbstransit.com.sg>

Estimate for

Bus No.: SBS8667A		Model: Scania KUB4X2(EEV), SD, AC, 2 Axle	
Acc. Report Date: 08/10/2021		Report No.: E43502021	
(A) Total for Parts:			
Stock Code	Description	Quantity	Total Material cost(\$)
		0	\$0.00
30122013	SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY <i>bt</i>	1	\$140.00
30122006	GAS JACK 0200N;RR ENG DOOR <i>bt</i>	2	\$40.00

- ☐ Parts cost: \$ **180**
☐ Contractor Labour cost: \$ **950 + gst**
☐ Workshop Labour cost: \$ **184** *Xnn*
☐ Advertisement Cost: \$ **0**
☐ Repair period: **3** days

- ☐ Tow Cost: \$ **0**
☐ Loss of use: \$ **LKK doesn't require** *Xng*
☐ Overheads: \$ **LKK doesn't require** *Xur*

Tanfhi 92495749
 -ap' 14/10/21 @ 1130am
 Resurvey before paint
 tanfhi @ 1140am
 3 days
 & CoR not finalise with w/s.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: