

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010536/GTF3E2

Date: 27/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMT1212P

Insured Vehicle No : SLD5522P

Date of Loss: 08/10/2021

Nature of Claim: TP

Claim No: 9584942416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT1212P**

Make & Model: MASERATI GRANTURISMO, 4.2 (A)

Engine No: M139P160514

Reg. Date: 27/08/2010 (Man. Year: 2010)

Chassis No: ZAMGH45C000053528

Colour: White

Odometer: 114986 km

Engine Capacity: 4244 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20

Rear Tyre Size: 245/35Z R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/10/2021

Date Inspected: 18/10/2021 Inspected At:

Jingkia Car Services (HQ)

BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK

AUTO POINT

Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$140,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT LH FENDER	Buckled	0.00 F	*- F
4	3		*FRT LH FENDER GRILLE	Necessary	0.00 F	*- F
5	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
6	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
7	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
8	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*- F
9	1		*FRT LH KNUCKLE ARM BEARING	Jammed	0.00 F	*- F
10	1		*FRT LH LOWER ARM	* Check	0.00 F	*- F
11	1		*FRT LH UPPER ARM	* Check	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >