

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010537/KVF3N2**Date:** 25/03/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80485109QMX
Claimant Vehicle No :	SJU5208G	Insured Vehicle No :	SNA7766G
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	638355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU5208G		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A)	Engine No:	4A910124039
Reg. Date:	15/12/2009 (Man. Year: 2009)	Chassis No:	JMYSRCY2A9U004517
Colour:	Metallic Red	Odometer:	203789 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,669.50	1,645.20	24.30	1.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	700.00	200.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,569.50	2,345.20	224.30	8.73
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	2,569.50	1,850.00	719.50	28.00
+ GST 7.00/7.00% (S\$)	179.87	129.50	50.37	28.00
Nett Amount (S\$)	2,749.37	1,979.50	769.87	28.00

INSPECTION

Date of Assignment:	13/10/2021	
Date Inspected:	14/03/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

FOR MANDATE ONLY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Mar 2022)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJU5208G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	810.00 FN	*810.00 FN
2	1		*FRONT BUMPER REINFORCEMENT	Bent	326.00 FN	*326.00 FN
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FN	*21.00 FN
4	1		*LH HEADLAMP	Cut	698.00 FN	*671.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	1,855.00	1,828.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	185.50	182.80
Total Parts (\$\$)	1,669.50	1,645.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMP.TO KNOCK & REPAIR FRT LH FENDER AND REALIGN THE SAME	New	400.00	300.00
2	PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT AND FRT LH FENDER	New	500.00	400.00
			Gross Labour Cost (\$\$)	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >