

TP 1st Cap. SMT5154A. 2019 March.
Leilin. Honda Fit Hybrid-1486CC.
GPS1341816

Front Bumper	Deformed	725.30	✓
Front Bumper Clips.	new	30(SN)	✓
Front Bumper Side Holder LH.	new	25.50	✓
Front Bumper Reinforcement	Dented	288.20	✓
Front Bumper Side Grille LH.	cut	145.30	✓
Headlamp LH.	crushed	1170.60	✓
Front Grille	crushed	382.90	✓
Front Grille Chrome Moulding	new	240.40	+
Front Grille Logo.	2	37.	✓
Front Grille Clips.	new	20(SN)	✓
Front Support Panel.	Repis	655.90	+
Air Con Condenser Side Guide	new	34.90	+

SMJ5154A.

Front Lt Fender. ^{Repair} 368.50 x

Front Lt Fender Hybrid Logo. ^{New} 48.80 ✓

Front Lt Fender Decorative Stickers. ^{New} 50(SN) 30(SN)

Front Bumper Lower Panel. ^{Repair} 298.40 x

2814.10 S/N: 80

2259.28

Panel Beating

Spray Painting

Wiring.

~~1000.~~ 500

~~800.~~ 500

1030.

~~50~~ 30

To remove condenser and to } 120 x
top up air con gas

To remove radiator and to } 120. x
top up coolant

total: 3369.28.

L/S: 27K.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sig: [Signature]

Date: