

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 3230S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,866.10	-
1	FRONT PANEL 'DYNA' EMBLEM (CONSISTENT)	NECESSARY	105.20	88.50
1	FRONT WINDSCREEN RUBBER (CONSISTENT)	NOT NECESSARY	433.10	-
1	FRONT CORNER PANEL GARNISH N/S (CONSISTENT)	WARPED / CRACKED	485.10	408.10
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	688.50	-
1	HEADLAMP LED N/S (CONSISTENT)	SCRATCHED	1,866.10	1,178.70
1	FRONT DOOR N/S (CONSISTENT)	DENTED/ BENT	1,955.30	1,794.20
1	FRONT DOOR OUTER HANDLE N/S (CONSISTENT)	TWISTED	422.50	204.30
1	FRONT DOOR ELECTRIC VIEWS BRACKET ASSY N/S (CONSISTENT)	NOT NECESSARY	1,550.10	-
1	FRONT DOOR INNER RUBBER N/S (CONSISTENT)	NOT NECESSARY	288.30	-
1	FRONT DOOR INNER PILLAR N/S (CONSISTENT)	TO REPAIR SEE LABOUR	899.10	-
1	SET FRONT DOOR ROC STICKER N/S (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT DOOR VISOR N/S (CONSISTENT)	NECESSARY	80.00	80.00
	LESS 25% DISCOUNT		-	-950.95
			10,689.40	2,852.85
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING .		80.00	40.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX FRONT WINDSCREEN .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX FRONT DASHBOARD .	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM .		80.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT PANEL AND FRONT DOOR INNER PILLAR N/S .		880.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	580.00
			2,890.00	1,200.00
	GRAND TOTAL		13,579.40	4,052.85

Report Ref No. CC4/ASM21010539/Ugs3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21010539/Ugs3q2

CHUA KANG SENG

**Licensed Appraiser**