

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010544/KUY3N2**Date:** 05/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00015982105	
<b>Claimant Vehicle No :</b>	SGP205J	<b>Insured Vehicle No :</b>	SBN96B	
Date of Loss:	11/10/2021	Nature of Claim:	TP	Claim No: SNM21D205804/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGP205J</b>		Engine No:	A788J804N13B16A
Make & Model:	BMW 320I, 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A)	Chassis No:	WBA3J92040J642367	
Reg. Date:	16/10/2014 (Man. Year: 2014)	Odometer:	42569 km	
Colour:	Metallic Blue			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,825.21	7,574.12	1,251.09	14.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,640.00	1,740.00	39.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,205.21</b>	<b>10,214.12</b>	<b>2,991.09</b>	<b>22.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,100.00</b>		
<b>(S\$)</b>	13,205.21	8,100.00	5,105.21	38.66
<b>+ GST 7.00/7.00% (S\$)</b>	924.36	567.00	357.36	38.66
<b>Nett Amount (S\$)</b>	<b>14,129.57</b>	<b>8,667.00</b>	<b>5,462.57</b>	<b>38.66</b>

**INSPECTION**

Date of Assignment:	13/10/2021	
Date Inspected:	15/10/2021	Inspected At: Falcon Air Auto Services Pte Ltd (HQ) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	8.0 days	

**Adjuster:** KENNETH KONG**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2021)

**Parts:** 143 BMW 320I 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGP205J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,284.75 FL	*1,284.75 FL
2	1		*LH REAR BUMPER SIDE RETAINER	Distorted	153.50 FL	*153.50 FL
3	1		*LH REAR FENDER	Bent	1,751.50 FL	*1,521.20 FL
4	1		*LH REAR FENDER TOP GARNISH	Serviceable	285.00 FL	*- FL
5	1		*LH REAR DOOR	Bent	1,380.20 FL	*1,380.20 FL
6	1		*LH REAR DOOR BLACK TAPE	Necessary	79.02 FL	*79.02 FL
7	1		*LH REAR DOOR GLASS OUTER MOULDING	Buckled	115.20 FL	*115.20 FL
8	1		*LH REAR DOOR GLASS REGULATOR	Bent	283.95 FL	*283.95 FL
9	1		*LH REAR DOOR GLASS REGULATOR MOTOR	Jammed	323.80 FL	*323.80 FL
10	1		*LH REAR DOOR INNER LOCK	Jammed	290.95 FL	*290.95 FL
11	1		*LH REAR DOOR INNER TRIM BOARD	Mtg Cracked	1,724.00 FL	*1,500.00 FL
12	1		*LH SIDE SKIRT	Serviceable	484.10 FL	*- FL
13	1		*LH REAR SPORT RIM	Dented	900.00 FL	*900.00 FL
14	1		*LH REAR DOOR WEATHERSTRIP (50%)	Necessary	177.04 FS	*93.18 FS
15	1		*SEALANT	Necessary	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,278.01</b>	<b>7,965.75</b>
<b>- List Item Discount on L Items 5.00/5.00% (S\$)</b>	452.80	391.63
<b>Total Parts (S\$)</b>	<b>8,825.21</b>	<b>7,574.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO TRANSFER LH REAR DOOR MECHANISM	New	100.00	60.00
3	TO REMOVE/REFIX TRIMS,SPEAKERBOARD,SEATS,ETC TO FACILITATE REPAIRS	New	280.00	120.00
4	TO RUSTPROOF ACCIDENT DAMAGE AREA	New	200.00	60.00
5	TO STRAIGHTEN LH ROCKER PANEL,LH FRONT DOOR,LH REAR FENDER INNER PANEL,LH B PILLAR,CUT OUT/RE-WELD LH REAR FENDER INCLUDING REPLACEMENT OF PARTS	New	1,700.00	900.00
6	TO SPRAY PAINT ON REAR BUMPER,LH REAR FENDER OUTER/INNER,LH REAR DOOR,LH FRONT DOOR,LH B PILLAR,LH ROCKER PANEL,LH SIDE SKIRT	New	1,800.00	1,300.00
7	TO CONDUCT WHEEL ALIGNMENT (COMPUTERISE)	New	120.00	60.00
8	TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE	New	60.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,380.00</b>	<b>2,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >