

# LONPAC INSURANCE BHD

#### UEN No S98FC5635C

Our Ref:

: 20/21/21/VC05/024535

Your Ref

: CS3/LPC21005639/R1tf3e2

Date

: 13 October 2021

M/s LKK Auto Consultants Pte Ltd

Singapore

#### RE-INSPECTION OF GBH6383P

We refer to the above accident.

Kindly proceed to conduct a re-inspection at the following:

Vehicle No.

: GBH6383P

Location

: Gold Autoworks Pte Ltd 48 Toh Guan Road

#01-119 Enterprise Hub Singapore 415875

Date/Time

: 20 October2021 - 10.00am

Contact

: Winston-98719488

We enclose the following documents:

- a) Survey report of GBH6383P
- b) Photos & repair bill of GBH6383P
- c) GIA report & photos of YP486B

We look forward to receiving your report within the next 10 days upon completion of the reinspection.

Yours faithfully



Gerald Poh

Senior Executive (Claims)

Email: mt claim@lonpac.com



Insurance 2010

#### **GERALD POH WEE BIN**

From:

SL LAW PRS <prs@sllaw.com.sg>

Sent:

Wednesday, 13 October 2021 3:09 pm

To:

GERALD POH WEE BIN

Cc:

**GOLD AUTOWORKS PTE LTD** 

Subject:

RE: Urgent Accident involving GBH6383P & YP486B on 4/5/2021. Our Ref:

PD.191672.LH [External General]

#### WITHOUT PREJUDICE

Dear Gerald,

We refer to the above matter.

Please be informed that our client's vehicle is available for re-inspection on 20 October 2021 @ 10am at GOLD AUTOWORKS PTE. LTD.

(48 TOH GUAN ROADS ENTERPRISE HUB, #01-119 SINGAPORE 608586). Contact person: WINSTON (98719488)

Please let us have your confirmation. Thank you.

Regards

Lheny

DID: 6909 9356

Fax: 6909 6246

Address: 133 New Bridge Road #13 - 01 Chinatown Point, Singapore 059413



This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

From: SL LAW PRS

Sent: Thursday, 26 August 2021 5:03 PM

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Subject: RE: Urgent Accident involving GBH6383P & YP486B on 4/5/2021. Our Ref: PD.191672.LH [External General]

#### WITHOUT PREJUDICE

Dear Sir/Madam

We refer to the above matter and our Letter of Demand.

Attached, please find our Letter of Demand and its supporting documents.

Thank you.



48 Toh Guan Rd East, Enterprise Hub #01-119, Singapore 608586

Email claims@goldautoworks.com.sg

Company Registration: 201716329M

Fax: 6264 5948

GST Registration No: 201716329M

Tax Invoice:

GA-21-GBH6383P

Customer Name

SHARP ENGINEERING & CONSTRUCTION PTE LTD

Vehicle No

GBH6383P

Make

TOYOTA

Model

DYNA 150

Chassis number

JTFAT35Y60K211159

Accident Date

4/May/21

Contact No

98719488

Mileage

NOT AVAILABLE

Attended By

WINSTON CHUA

Delivery Date

11/6/2021

5

| 5/N | DESCRIPTION     | QTY | UNIT PRICE | AMOUNT       |
|-----|-----------------|-----|------------|--------------|
| 1   | LUMP SUM REPAIR | 1   | C-C-Horse  | \$ 26,070.00 |
| -   |                 |     |            |              |
| -   |                 |     |            |              |

#### SINGAPORE DOLLARS

1) GOODS SOLD ARE NOT RETURNABLE.

2) ALL CHEQUE TO BE CROSSED AND DRAWN IN FAVOUR OF GOLD AUTO WORKS PTE LTD

GRAND TOTAL

26,070.00

1,824.90 \$

NETT TOTAL

27,894.90

FOR & ON BEHALF OF NO GOLD AUTOWORKS PTE LITD

AUTHORISED SIGNATURE AND COMPANY STAMP

LESS DISCOUNT

TOTAL PAYMENT

27,894.90

BALANCE

To. M/s. Sharp Engineering & Construction Pte. Ltd.

Invoice No.

HA 2107-09

Co. 48 Toh Guan Road East

Date

03/07/2021

#01-119 Enterprise Hub Singapore 608586

|                  | Amount (SGD)   |                 |
|------------------|--|-----------------|
| Services rendere | ed for appraiser / inspection report :-              |                 |
| Survey Fee       |  |                 |
| Photographs      |  |                 |
| Transport Fees   |  |                 |
| Re-inspection Fe | es   |                 |
|                  | Total:   | SGD: \$ 1,278.0 |
| SGD Dollar :     | One Thousand Two Hundred Seventy Eight Dollars Only. |                 |
| Our Reference    | PAS/TP/0270521                                       |                 |
| Vehicle No.      | GBH6383P   |                 |
| Make & Model     | Toyota Dyna 150                                      |                 |
|                  | Third Party Claim                                    |                 |

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD" Please indicate our "INVOICE NO." on the reverse side of the cheque Should you have any enquiries, please do not hesitate to contact us.



Correspondence Mail Address My Mail Box 886259 Singapore 919191 Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

### VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0270521

Date of Report

03/07/2021

To M/s. Sharp Engineering & Construction Pte. Ltd.

Date of Assignment

10/05/2021

Co. 48 Toh Guan Road East

Report requested by

M/s. Sharp Engineering & Co.

#01-119 Enterprise Hub Singapore 608586

Date of Accident Date of Inspection 04/05/2021

10/05/2021

Claim No.

Third Party Claim

Policy No.

#### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

GBH6383P

Make & Model

Toyota Dyna 150

06/08/2018

Engine Capacity (cc)

2982cc

Mileage (km)

Not Available

Date of Registration

Chassis Frame No.

JTFAT35Y60K211159

Colour

Blue

Engine No.

1KD2814325

#### TYRE CONDITION

Front LH

10 mm

Front RH

10 mm

Make

Habilead

Make

Habilead

Rear LH

6 mm / 6 mm

Rear RH

6 mm 6 mm

Make

: Yokohama

Make

: Yokohama

Road wheels Type: Standard

(The above represents the approximate remaining life of tyre treads)

#### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

Good

Paintwork

Good

Handbrake

Serviceable

Footbrake

Serviceable

Serviceable

Steering

Apparent Engine Modification

Nil

#### PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Gold Autoworks Pte Ltd

48, Toh Guan Road East, #01-119. Enterprise Hub, Singapore 608586

#### ASSESSMENT

Repairer's Estimate

\$ 38,261.23

Revised Amount

\$ 32,593.68

Less Excess

: 5

Recommended Reserve

\$ 26,070.00 (Lump Sum)

Estimated Normal Period of Repairs

21 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall in held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate. distribute, copy any information convined herein or use of this communication is strictly prohibited.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address My Mail Box 886259 Singapore 919191
Mobile 9295 2204 Fax 6722 8508 Email pasves@hotmail.com

Business Reg 201404434D

Vehicle No: GBH6383P

Report No.: PAS/TP/0270521

#### GENERAL REMARKS

WITHOUT PREJUDICE

#### THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd. 48. Toh Guan Road East, #01-119. Enterprise Hub. Singapore 608586.

(Subsequent inspections have been conducted)

#### POINT OF IMPACT

At the front RH portion.

#### DAMAGES

The front windscreen, front wiper panel, front panel assy. RHF corner panel, front grille assy, headlamps, front bumper, dashboard assy, combination meter assy, a/c evaporator & blower, airbags & seatbelts, roof panel, RHF door pillars, front floor panel, RH door, RHF wheel arch panel, RHR door pillars, cabin rear panel, rear deck front guard, etc.

Other parts were also found damaged. (See schedule for details)

#### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$32,593.68.

#### CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$26.070.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly.

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address My Mail Box 886259 Singapore 919191

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No: GBH6383P

Report No.: PAS/TP/0270521

## APPRAISEMENT SCHEDULE

| S/No | . Qty    | Parts Descriptions                         | Condition                |          | W 0455745 | imate (S\$) |    | Our<br>nent (S\$) |
|------|----------|--|--------------------------|----------|-----------|-------------|----|-------------------|
|      |          |  |                          |          |           |             |    | 1 402 10          |
| 1    | 1 pc     | Frt windscreen                             | Broken                   |          | \$        | 1.582.40    | S  | 1.582.40          |
| 2    | 1 pc     | Frt windscreen moulding                    | Necessary                |          | \$        | 372.90      | \$ | 372.90            |
|      | 1 pc     | Wiper blade RH                             | Broken Dislodged/Missing |          | S         | 81.20       | S  | 81.20             |
| 4    | 1 pc     | Wiper arm RH                               | Broken Dislodged/Missing |          | S         | 114.50      | S  | 114.50            |
| 5    | 1 pc     | Wiper arm cap RH                           | Broken                   |          | ,         | 9.70        | S  | 9.70              |
| 6    | 1 pc     | Wiper arm cap link rod assy                | Dented Damaged           |          | S         | 298.70      | S  | 298.70            |
| 7    | 1 pc     | Wiper motor                                | Refit                    |          | \$        | 760.70      | S  | ***               |
| 8    | 1 pc     | Frt wiper panel                            | Dented                   |          | S         | 314.80      | S  | 314.80            |
| 9    | 1 pc     | Frt corner panel RH                        | Broken Dislodged/Missing |          | S         | 279.30      | S  | 279.30            |
| _ 10 | 1 pc     | Frt panel assy                             | Dented                   |          | 5         | 1,206.20    | S  | 1.206.20          |
| 11   | 1 pc     | Frt emblem (Logo)                          | Necessary                |          | 5         | 74.00       | \$ | 74.00             |
| 12   | I pc     | Frt emblem (Dyna)                          | Necessary                |          | 5         | 63.90       | S  | 63.90             |
| 13   | I pc     | Frt grille assy                            | Broken                   |          | 5         | 600.50      | S  | 600.50            |
| 14   | 8 pcs    | Frt grille clip                            | Necessary \$             | 2.20     | S         | 17.60       | 5  | 17.60             |
| 15   | 2 pcs    | Headlamp R/L                               | Broken Cracked S         | 1.188.40 | \$        | 2,376.80    | S  | 2,376.80          |
| 16   | 1 pc     | Frt bumper                                 | Dented                   |          | S         | 748.90      | 5  | 748.90            |
| 17   | 1 pc     | Frt bumper bracket RH                      | Dented                   |          | S         | 304.80      | 5  | 304.80            |
| 18   | 1 pc     | Frt cabin mounting support assy            | Realign                  |          | \$        | 1,136.80    | S  | ter               |
| 19   | 1 pc     | Dashboard                                  | Dented/Cracked           |          | S         | 1,197.30    | S  | 1,197.30          |
| 20   | 1 pc     | Dashboard audio speaker RH                 | Dented/Damaged           |          | \$        | 107.40      | S  | 107.40            |
| 21   | 1 pc     | Dashboard reinforcement                    | Bent/Distorted           |          | S         | 723.10      | S  | 723.10            |
| 22   | I pc     | Combination meter assy                     | Loop Broken              |          | S         | 1.450.80    | 8  | 1,450.80          |
| 23   | 1 pc     | Combination meter outer cover              | Cracked                  |          | \$        | 298.30      | S  | 298.30            |
| 24   | 1 pc     | Dashboard side cup garnish RH              | Dented/Cracked           |          | \$        | 100.60      | S  | 100.60            |
| 25   | 1 pc     | Dashboard side cup garnish LH              | Dented/Cracked           |          | \$        | 212.30      | 5  | 212.30            |
| 26   | 1 pc     | Dashboard center instrument cluster        |                          |          | \$        | 322.10      | S  | 322.10            |
| 27   | 1 pc     | Brake fluid reservoir tank                 | Dented/Distorted         |          | 5         | 88.90       | S  | 88.90             |
| 28   | 1 pc     | Brake master pump assy                     | Refit                    |          | S         | 546.70      | S. |                   |
| 29   | 1 pc     | Brake booster pump assy                    | Refit                    |          | \$        | 1,204.10    | 5  | 200 E-10 00 E-10  |
| 30   | 200      | Brake pump bracket                         | Dented/Distorted         |          | \$        | 300.50      | S  | 300.50            |
| 31   | 1 pc     | Accelerator pedal                          | Cracked Damaged          |          | \$        | 304.10      | S  | 304.10            |
| 32   |          | Brake pedal                                | Serviceable              |          | S         | 110.40      | S  |                   |
| 33   | S        | Brake vacuum reservoir tank                | Dented                   |          | S         | 192.00      | \$ | 192.00            |
| 34   | 1 pc     | Brake vacuum warning switch                | Refit                    |          | S         | 119.90      | S  |                   |
| 35   |          | A/c blower assy                            | Broken                   |          | S         | 420.60      | S  | 420.60            |
| 36   |          | A/c evaporator assy                        | Broken                   |          | S         | 2,861.30    | S  | 2,861.30          |
| 37   | 0.00     | Steering wheel                             | Serviceable              |          | 5         | 1.260.10    | S  | 1                 |
| 38   |          | Steering wheel column cover                | Cracked                  |          | S         | 62.70       | S  | 62.70             |
| 39   |          | Driver airbag                              | Deployed                 |          | S         | 2,752.10    | S  | 2,752.10          |
| 40   | 100      | Driver airbag spiral cable                 | Affected/Necessary       |          | S         | 452.40      | S  | 452.40            |
|      | 0.11.5.0 | Passenger airbag                           | Deployed                 |          | S         | 4.242.40    | 5  | 4,242.40          |
| 41   | 30000    |  | January d'Orotonoioner   |          | 1125      |             |    |                   |
| 42   | 2 pcs    | Frt seatbelt R/L                           | Activated S              | 1.001.90 | S         | 2,003.80    | \$ | 2,003.80          |
| 2.00 | 1917-255 | Airbag control unit                        | Affected Necessary       |          | \$        | 885.10      | S  | 885.10            |
| 43   | 1 pc     | Airbag control unit                        | Affected Necessary §     | 219.10   | \$        | 438.20      | 5  | 438.20            |
| 44   |          | s Airbag sensor<br>RHF door pillar garnish | Sented/Cracked           | 217:10   | \$        | 103.60      | S  | 103.60            |
| 45   |          | warm a line number                         | Denied/Distorted         |          | \$        | 588.10      | S  | 588.10            |
| 46   |          | part 1 Managin Formaniant                  | Dented/Di-orted          |          | \$        | 277.30      | S  | 277.30            |
| 47   |          |  | Dented/Distorted         |          | \$        | 332.00      | S  | 332.00            |
| 48   | 1 pc     | RHF door pillar inner                      |                          |          | 3         | 332.00      | 3  | 332.00            |



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address My Mail Box 886259 Singapore 919191
Mobile 9295 2204 Fax 6722 8508 Email pasves@hotmail.com

Business Reg 201404434D

| S/No.    |         | GBH6383P                                    |                           |                  |       |           |                         |             |                   |
|----------|---------|---|---------------------------|------------------|-------|-----------|-------------------------|-------------|-------------------|
|          | Qty     | Parts Descriptions                          | Condition                 |                  |       | 000011155 | pairer's<br>imate (S\$) |             | our<br>nent (S\$) |
|          |         |   |                           |                  | 6.    | \$        | 34.301.90               | _S          | 29,163,20         |
| 200      |         | C. O annual                                 | Dented/Buckled            |                  |       | 5         | 786.90                  | 5           | 786.90            |
| 49       | 1 pc    | Frt floor panel<br>RH side mirror assy      | Refit                     |                  |       | 5         | 310.70                  | S           |                   |
| 50       | 1 pc    | [14] [16] [16] [16] [16] [16] [16] [16] [16 | Dented/Distorted          |                  |       | \$        | 1,811.60                | S           | 1,811.60          |
| 51       | 1 pc    | RH door<br>RH door quarter garnish          | Cracked                   |                  |       | 5         | 52.60                   | S           | 52.60             |
| 52       | 1 pc    | RH door glass outer moulding                | Torn/Deformed             |                  |       | S         | 107.30                  | S           | 107.30            |
| 53       | 1 pc    | RH door glass outer mountaing               | Serviceable               |                  |       | 5         | 715.30                  | S           | 9.5               |
| 54       | 1 pc    | RH door run channel                         | Reusable                  |                  |       | S         | 231.30                  | \$          | 2.6               |
| 55       | l pc    | RH door run channel frame                   | Dented/Bent               |                  |       | \$        | 98.10                   | 5           | 98.10             |
| 56       | 1 pc    | RH door front seal                          | Torn/Necessary            |                  |       | \$        | 44.20                   | S           | 44.20             |
| 57       | 1 pc    | RH door outer handle                        | Loop Cracked              |                  |       | 8         | 194.40                  | S           | 194.40            |
| 58       | 1 pc    | RH door hinge                               | Dented/Bent               | S 89.5           | 0     | \$        | 179.00                  | S           | 179.00            |
| 59       | 100     | RH door checker                             | Dented/Bent               | AT. A            |       | S         | 149.70                  | S           | 149.70            |
| 50       | 1 pc    | RH door inner trim                          | Dented/Cracked            |                  |       | 5         | 566,90                  | S           | 566.90            |
| 61       | I pc    | RH door regulator assy                      | Dented/Jammed             |                  |       | 8         | 338.10                  | S           | 338.10            |
| 62       | I pc    | RH door regulator motor                     | Dented/Damaged            |                  |       | 5         | 580.60                  | S           | 580.60            |
| 63       | 1 pc    | RH door audio speakers                      | Refit                     |                  |       | \$        | 107.40                  | S           | -                 |
| 64       | 1 pc    | RH door lock                                | Dented/Jammed             |                  |       | 5         | 300.50                  | S           | 300.5             |
| 65       | 1 pc    | RH door arch seal                           | Torn/Necessary            |                  |       | S         | 96.40                   | S           | 96.4              |
| 66       | 1 pc    | RH door weatherstrip                        | Torn/Necessary            |                  |       | 8         | 195.60                  | S           | 195.6             |
| 67<br>68 | 1 pc    | RH door inner seal                          | Necessary                 |                  |       | S         | 93.10                   | S           | 93.10             |
| 69       | 1 pc    | RHF door arch garnish                       | Dented/Deformed           |                  |       | 5         | 205.10                  | \$          | 205.10            |
| 70       | 1 pc    | RHF step plate                              | Dented/Cracked            |                  |       | \$        | 287.40                  | \$          | 287.4             |
| 71       | 1 pc    | RHF step plate bracket                      | Dented/Bent               |                  |       | \$        | 112.10                  | S           | 112.1             |
| 72       | 1 pc    | RH door rear pillar                         | Dented/Distorted          |                  |       | 5         | 546.20                  | S           | 546.2             |
| 73       | 1 pc    | RH door rear pillar emblem                  | Necessary                 |                  |       | S         | 47.90                   | S           | 47.9              |
| 74       | 1 pc    | Roof panel                                  | Dented/Repair             |                  |       |           | (Refer                  | labour no.  | 5.9 & 10          |
| 75       | 8 - 300 | Cabin rear panel                            | Dented/Repair             |                  |       |           | (Refer                  | labour no.  | 5.9 & 10          |
| 76       | 1 pc    | RH door rear pillar inner member            | Dented/Repair             |                  |       |           | (Refer                  | labour no.  | 5.9 & 10          |
| 77       | 1 pc    | Rr deck front guard                         | Dented Repair             |                  |       |           | (Ref                    | er labour i | 10.9 & 10         |
| 37.7     | 1 pc    | RI GCCK HOM guard                           | TO 11 (1970 200 4 (1971)) |                  |       | -         | 42,460.30               | 5           | 35.956.9          |
|          |         |   |                           | Less Discour     | 1 25% |           |                         |             | 8,989.2           |
|          |         |   | List                      | t Parts Sub-Tota |       | _         | 31.845.23               | -           | 26.967.6          |
| 1        | 1 m     | Frt panel scalant                           | Necessary                 | S                | /N    | 5         | 50.00                   | S           | 40.0              |
| 2        | 1 pc    | RHF door pillar scalant                     | Necessary                 | S                | N     | \$        | 50.00                   | S           | 40.0              |
| 3        | 1 pc    | RH door rear pillar scalant                 | Necessary                 |                  | N     | \$        | 50.00                   | \$          | 40.0              |
| 4        | 1 pc    | Brake fluid                                 | Necessary                 |                  | N     | 8         | 20.00                   | 5           | 20.0              |
| 5        | 1 pc    | ERP bracket                                 | Necessary                 |                  | N     | 5         | 26,00                   | S           | 26.0              |
| 6        | 1 pc    | Car stereo receiver unit                    | Dented/Damaged            |                  | N.    | 5         | 250.00                  | S           | 250.0             |
| જ        | 11.5    | 76770 C                                     | Specia                    | al Nett Sub-Tota | al    | \$        | 446.00                  | S           | 416.0             |
|          |         |   |                           |                  |       |           |                         |             |                   |
|          |         |   |                           | Parts Tota       | al:   | \$        | 32,291.23               | S           | 27,383.6          |



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address My Mail Box 886259 Singapore 919191 Mobile 9295 2204 Fax 6722 8508 Email pasvos@hotmail.com

Business Reg 201404434D

| No. Labour Descriptions  | S S      | 70.00<br>120.00<br>350.00 |    | 50.00<br>120.00 |
|--|----------|---------------------------|----|-----------------|
| To check electrical system, repair wire harness and focus headlamp.  To remove, replace and reinstall front windscreen.  To remove, replace and reinstall dashboard assy.  To remove and reinstall a/c blower, a/c evaporator and a/c pipings for necessary repairs. | \$<br>\$ | 120.00                    | s  | 120.00          |
| To remove, replace and reinstall dashboard assy.  4 To remove and reinstall a/c blower, a/c evaporator and a/c pipings for necessary repairs.  | \$       | A-TEXALING III            |    | 17 STATUTE EX   |
| 4 To remove and reinstall a/c blower, a/c evaporator and a/c pipings for necessary repairs.  |          | 350.00                    | \$ | 300.00          |
|  |          |                           |    | 200.00          |
|  | S        | 150.00                    | s  | 120.00          |
| 5 To remove and reinstall interior trims, garnishes, seats, etc. for necessary repairs.<br>(Include remove roof lining and carpet)   | S        | 150.00                    | S  | 120.00          |
| 6 To vacuum, clean up broken glass debris. To provide cleaning service on interior trimming<br>and seats.  | g<br>S   | 100.00                    | s  | 80.00           |
| 7 To remove, replace front airbags, seat belts, sensors and airbag ECU.<br>(Include reset SRS ECU)   | S        | 350.00                    | S  | 300,00          |
| 8 To transfer RH door component parts to new door.   | \$       | 100.00                    | S  | 80.00           |
| 9 To straighten, repair, realign on affected area and replace damaged parts.   | \$       | 2,200.00                  | \$ | 1,980.00        |
| 10 To spray painting, blending on affected and adjacent area.  | S        | 2.200.00                  | S  | 1.920.00        |
| 11 To spray anti-rust coating on new and affected panels.  | S        | 60.00                     | \$ | 60.00           |
| 12 Towing.   | 5        | 120.00                    | S  | 80,00           |
| Labour Total:  | \$       | 5,970.00                  | S  | 5,210.00        |

#### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$

Under normal circumstances, the repairs should be completed within a reasonable period

21 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

228 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.