



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21005639/R1tf3e2-1	
			Date: 14/01/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	YP 486B	Veh. Inspected	GBH 6383P	
Policy No.	Z20VC05006515	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024535	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	13/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 5MT	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y60K211159	Colour	BLUE	
Odometer	28041 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	HABILEAD	7 mm	
L/H Front Tyre	195 R15C	HABILEAD	7 mm	
R/H Rear Tyre	155 R12C (D)	HABILEAD	6/6 mm	
L/H Rear Tyre	155 R12C (D)	HABILEAD	6/6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	04/05/2021	Inspection Date	03/12/2021	
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	