

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010547/KVY3N2**Date:** 26/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00007212000

Claimant Vehicle No : EZ888J **Insured Vehicle No :** SKU1292B

Date of Loss: 09/10/2021 Nature of Claim: TP Claim No: SNM21D205755/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EZ888J**

Make & Model: AUDI A8, 3.0 (A) Engine No: CZS016971

Reg. Date: 18/12/2018 (Man. Year: 2018) Chassis No: WAUZZZF83KN006344

Colour: Metallic Brown Odometer: 71797 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35ZR21 Rear Tyre Size: 275/35ZR21

Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,063.32	32,179.72	16,883.60	34.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,530.00	2,320.00	60.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,913.32	33,709.72	19,203.60	36.29
Approved Total (Overridden) (S\$)		26,600.00		
(S\$)	52,913.32	26,600.00	26,313.32	49.73
+ GST 7.00/7.00% (S\$)	3,703.93	1,862.00	1,841.93	49.73
Nett Amount (S\$)	56,617.25	28,462.00	28,155.25	49.73

INSPECTION

Date of Assignment: 13/10/2021

Date Inspected: 14/10/2021 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	143	AUDI A8 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EZ888J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	3,840.00 FL	*3,767.00 FL
2	1		*FRONT BUMPER RETAINERS	O/s Cracked	219.00 FL	*109.50 FL
3	1		*FRONT BUMPER SECURING STRIP	Serviceable	384.50 FL	*- FL
4	1		*FRONT BUMPER CHROME GRILLE LOWER CENTER	Serviceable	466.00 FL	*- FL
5	2		*FRONT BUMPER CHROME STRIP - SIDE	Serviceable	379.00 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP COVER O/S	Missing	591.00 FL	*341.00 FL
7	1		*FRONT BUMPER DISTANCE RADAR O/S	Serviceable	564.80 FL	*- FL
8	1		*FRONT GRILLE ASSY	Mtg Cracked	2,833.00 FL	*2,477.00 FL
9	1		*FRONT GRILLE INNER TOP BRACKET COVER	Serviceable	199.00 FL	*- FL
10	1		*FRONT GRILLE INNER LOWER BRACKET	Serviceable	176.50 FL	*- FL
11	1		*FRONT FENDER O/S	Repair	2,998.00 FL	*- FL
12	1		*FRONT FENDER INNER SUPPORT O/S	Repair	152.00 FL	*- FL
13	1		*INTERCOOLER O/S	Bent / Punctured	2,666.00 FL	*1,961.00 FL
14	1		*INTERCOOLER OUTER GUIDE O/S	Serviceable	64.30 FL	*- FL
15	1		*HEADLAMP ASSY O/S	Cut	16,081.00 FL	*13,928.00 FL
16	1		*HEADLAMP TOP GARNISH O/S	Serviceable	167.30 FL	*- FL
17	1		*FRONT REINFORCEMENT	Bent	1,253.00 FL	*1,051.00 FL
18	2		*FRONT REINFORCEMENT SUPPORT BRACKET	Repair	59.00 FL	*- FL
19	1		*FRONT FENDER INNER SHIELD FRONT O/S	Cracked	94.50 FL	*94.50 FL
20	1		*FRONT FENDER INNER SHIELD REAR O/S	Serviceable	422.00 FL	*- FL
21	1		*FRONT BUMPER LOWER COWLING	Serviceable	261.50 FL	*- FL
22	1		*FRONT BUMPER SPONGE	Cracked	126.50 FL	*126.50 FL
23	2		*FRONT BUMPER SENSOR HOLDER O/S	Necessary	90.40 FL	*90.40 FL
24	1		*FRONT BUMPER SENSOR WIRE HARNESS	Serviceable	934.60 FL	*- FL
25	1		*RADIATOR ASSY	Serviceable	1,890.00 FL	*- FL
26	1		*RADIATOR ASSY SIDE DEFLECTOR O/S	Serviceable	35.50 FL	*- FL
27	1		*HEADLAMP WASHER NOZZLE COVER O/S	Missing	73.40 FL	*73.40 FL
28	1		*HEADLAMP WASHER NOZZLE O/S	Cracked	280.00 FL	*280.00 FL
29	1		*INTERCOOLER AIR DUCT O/S	Serviceable	128.90 FL	*- FL
30	1		*FRONT BUMPER CAMERA	Shorted	1,729.00 FL	*1,003.00 FL
31	1		*FRONT BUMPER CAMERA HARNESS	Serviceable	445.70 FL	*- FL
32	1		*A/C CONDENSER	Serviceable	952.00 FL	*- FL
33	1		*FRONT WHEEL KNUCKLE O/S	Bent	904.00 FL	*785.60 FL
34	1		*FRONT CONTROL ARM O/S	Bent	702.50 FL	*702.50 FL
35	1		*FRONT LOWER ARM O/S	Bent	746.50 FL	*687.20 FL
36	1		*FRONT SHOCK ABSORBER O/S	Bent	4,054.00 FL	*3,780.00 FL
37	1		*FRONT ENDLINK O/S	Serviceable	126.50 FL	*- FL
38	2		*FRONT REINFORCEMENT LOWER BRACKET	Repair	112.60 FL	*- FL
39	8		*BONNET INSULATOR ATTACHMENTS	Not Necessary	44.00 FS	*- FS
40	8		*SUPPORT PANEL GARNISH ATTACHMENTS	Not Necessary	44.00 FS	*- FS
41	10		*FRONT BUMPER ATTACHMENTS	Necessary	55.00 FS	*55.00 FS
42	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
43	1		*FRONT NUMBER PLATE	Serviceable	55.00 FS	*- FS
44	10		*WHEEL HOUSING LINER ATTACHMENTS-LH	Not Necessary	55.00 FS	*- FS
45	1		*FRONT WHEEL ORIGINAL 21 RH	Bent	2,431.00 FS	*1,850.00 FS
46	1		*FRONT BUMPER SENSOR RH	Shorted	736.00 FS	*265.00 FS

Report was unsubmitted during this print-out.

5/26/22, 4:21 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT TYRE 21 RH (\$450) (70%)	Punctured	650.00 FS	*315.00 FS
48	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					51,423.50	33,742.60
- List Item Discount on L Items 5.00/5.00% (\$\$)					2,360.18	1,562.88
Total Parts (\$\$)					49,063.32	32,179.72
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	1,400.00	500.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS.	New	150.00	30.00
3	TO REMOVE AND REPLACE A/C CONDENSER. TO RECHARGE SYSTEM & CHECK A/C FUNCTIONALITY.	New	150.00	0.00
4	TO REMOVE AND REFIT O/S FRONT TYRE & RIM FOR REPLACEMENT. TO PERFORM TYRE BALANCING.	New	100.00	20.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL.	New	1,200.00	600.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	New	100.00	0.00
7	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	New	300.00	200.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	New	150.00	60.00
9	TO RESET BOTH FRONT BUMPER DISTANCE SENSOR & CAMERA INCLUDING REPROGRAMMING SYSTEM USING DIAGNOSTIC EQUIPMENT.	New	300.00	120.00
Gross Labour Cost (\$\$)			3,850.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >