

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010548/BVY3N2**Date:** 23/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00092432106

Claimant Vehicle No : SMY6969E **Insured Vehicle No :** SGY5868R

Date of Loss: 11/10/2021 Nature of Claim: TP Claim No: SNM21D205833/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY6969E**

Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27491030665928

Reg. Date: 10/08/2016 (Man. Year: 2016) Chassis No: WDD2050402R191424

Colour: White Odometer: 31600 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35ZR19 Rear Tyre Size: 235/35ZR19

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,525.12	9,529.94	6,995.18	42.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,740.00	1,880.00	51.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,145.12	11,269.94	8,875.18	44.06
Approved Total (Overridden) (\$\$)		9,000.00		
(\$\$)	20,145.12	9,000.00	11,145.12	55.32
+ GST 7.00/7.00% (\$\$)	1,410.16	630.00	780.16	55.32
Nett Amount (\$\$)	21,555.28	9,630.00	11,925.28	55.32

INSPECTION

Date of Assignment: 07/11/2021

Date Inspected: 14/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2022)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY6969E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,355.00 FL	*2,028.30 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	53.00 FL	*53.00 FL
3	1		*BOOTLID LOCK	Not Damaged	287.00 FL	*- FL
4	1		*REAR BUMPER (AMG)	Broken	1,756.00 FL	*1,756.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Broken	233.00 FL	*233.00 FL
6	1		*REAR BUMPER LOWER GARNISH RH REVERSE SENSOR	Short Circuit	178.00 FL	*178.00 FL
7	1		*REAR BUMPER LOWER GARNISH LH REVERSE SENSOR	Short Circuit	178.00 FL	*178.00 FL
8	1		*REAR BUMPER TOWING COVER	Dislodged	55.70 FL	*55.70 FL
9	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Damaged	178.00 FL	*- FL
10	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Damaged	178.00 FL	*- FL
11	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	28.00 FL	*28.00 FL
12	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Damaged	435.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	620.00 FL	*620.00 FL
14	1		*REAR BUMPER RH SIDE RETAINER	Necessary	60.80 FL	*60.80 FL
15	1		*REAR BUMPER RH BRACKET	No such part	53.60 FL	*- FL
16	1		*REAR BUMPER LH SIDE RETAINER	Necessary	60.80 FL	*60.80 FL
17	1		*REAR BUMPER LH BRACKET	No such part	53.60 FL	*- FL
18	1		*REAR BUMPER CENTRE BRACKET	Broken	98.30 FL	*45.00 FL
19	1		*RH TAILLAMP	Broken	765.00 FL	*454.00 FL
20	1		*RH TAILLAMP LOWER BRACKET	Broken	85.00 FL	*85.00 FL
21	1		*LH TAILLAMP	Broken	765.00 FL	*454.00 FL
22	1		*LH TAILLAMP LOWER BRACKET	Broken	85.00 FL	*85.00 FL
23	1		*END PANEL	Dented	1,545.00 FL	*980.00 FL
24	1		*END PANEL INNER GARNISH	Broken	156.00 FL	*156.00 FL
25	1		*REAR FENDER RH INNER TRIM	Torn	654.00 FL	*365.00 FL
26	1		*REAR FENDER LH INNER TRIM	Not Damaged	654.00 FL	*- FL
27	1		*SPARE TYRE TOP BOARD	Not Damaged	513.00 FL	*- FL
28	1		*SPARE TYRE PANEL	Broken	391.00 FL	*391.00 FL
29	1		*REAR LH EXHAUST SILENCER	Not Damaged	1,260.50 FL	*- FL
30	1		*REAR LH EXHAUST SILENCER GASKET	Not Damaged	60.50 FL	*- FL
31	1		*REAR RH EXHAUST SILENCER	Not Damaged	1,260.50 FL	*- FL
32	1		*REAR RH EXHAUST SILENCER GASKET	Not Damaged	60.50 FL	*- FL
33	1		*REAR BUMPER LOWER DIFFUSER (AFTER-MARKET)	Broken	780.00 FS	*780.00 FS
34	1		*REAR BUMPER RH EXHAUST CHROME FINISHER (AMG)	Dented	960.00 FS	*600.00 FS
35	1		*REAR BUMPER LH EXHAUST CHROME FINISHER (AMG)	Dented	960.00 FS	*600.00 FS
36	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
38	1		*SPARE TYRE PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,036.80	10,356.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,511.68	826.66
Total Parts (\$\$)	16,525.12	9,529.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,300.00	600.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	250.00	80.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
7	REMOVE AND REPLACE EXHAUST SILENCERS AND HEAT SHIELD TO ASSIST REPAIR	New	250.00	0.00
8	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO ASSIST REPAIR	New	120.00	80.00
9	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE AFTER REPAIR	New	220.00	120.00
Gross Labour Cost (\$)			3,620.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >