

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010552/KPS3Q2
Date: 15/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100494796
Claimant Vehicle No :	SKS1206L	Insured Vehicle No :	SLJ6974E
Date of Loss:	12/10/2021	Nature of Claim:	TP
		Claim No:	1846072166SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS1206L		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRX498356
Reg. Date:	26/03/2015 (Man. Year: 2015)	Chassis No:	MR053REH104529501
Colour:	Metallic Silver	Odometer:	171129 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Delinte 9 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Delinte 9 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,954.45	7,963.20	4,991.25	38.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,900.00	750.00	28.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,604.45	9,863.20	5,741.25	36.79
Approved Total (Overridden) (S\$)		7,850.00		

(S\$)	15,604.45	7,850.00	7,754.45	49.69
+ GST 7.00/7.00% (S\$)	1,092.31	549.50	542.81	49.69
Nett Amount (S\$)	16,696.76	8,399.50	8,297.26	49.69
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,706.95		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment: 13/10/2021

Date Inspected: 13/10/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
 Singapore 575644

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,028.10 FL	*1,028.10 FL
2	1		*BONNET LOCK	Bent	178.40 FL	*178.40 FL
3	1		*BONNET HINGE	Bent	59.90 FL	*59.90 FL
4	1		*SUPPORT PANEL	Bent	977.60 FL	*977.60 FL
5	1		*AIRCON CONDENSER	Serviceable	1,404.30 FL	*- FL
6	1		*RADIATOR	Serviceable	1,764.00 FL	*- FL
7	1		*FAN MOTOR	Serviceable	580.10 FL	*- FL
8	1		*FAN BLADE	Serviceable	190.20 FL	*- FL
9	1		*FAN COWLING	Serviceable	278.10 FL	*- FL
10	1		*FRONT GRILLE W CHROME	Cracked	379.10 FL	*379.10 FL
11	2		*HEADLAMP HID	Mtg Cracked	5,608.00 FL	*5,608.00 FL
12	1		*HEADLAMP TOP CHROME MOULDING	O/S Mtg Cracked	275.40 FL	*137.70 FL
13	1		*FRONT BUMPER	Bent / Cracked	458.00 FL	*458.00 FL
14	1		*FRONT BUMPER ENFORCEMENT	Bent	379.20 FL	*379.20 FL
15	2		*FRONT BUMPER RETAINER	Distorted	164.60 FL	*164.60 FL
16	1		*FRONT FENDER	O/S Buckled / N/S Repair	1,522.80 FL	*591.60 FL
17	2		*FENDER COWLING LH & RH	Serviceable	326.80 FL	*- FL
18	1		*COWLING CLIP	Not Necessary	38.00 FL	*- FL
19	1		*BUMPER LOWER GRILLE	Dented	122.80 FL	*122.80 FL
20	1		*LOWER GRILLE	Serviceable	128.40 FL	*- FL
21	2		*FOGLAMP	Serviceable	496.40 FL	*- FL
22	1		*FOGLAMP COVER	O/S Dented	225.80 FL	*112.90 FL
23	1		*BRACE PANEL	Bent	190.20 FL	*190.20 FL
24	1		*ENGINE LOWER CENTER COVER	Serviceable	135.80 FL	*- FL
25	1		*ENGINE LOWER SIDE COVER RH	Cracked	153.50 FL	*153.50 FL
26	1		*ENGINE LOWER SIDE COVER LH	Serviceable	131.10 FL	*- FL
27	20		*CLIP	Necessary	76.00 FL	*76.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	17,272.60	10,617.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,318.15	2,654.40
Total Parts (\$\$)	12,954.45	7,963.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REPLACE RADIATOR ,AIRCON CONDENSER ,FAN ASSY ,RECHARGE AIRCON GAS	New	250.00	100.00
2	TO REMOVE DAMAGE PARTS AND ATTACHMENTS CUT AND WELD DAMAGED FRONT PANEL AND FENDER STRAIGHTEN FRONT CHASSIS WHERE NECESSARY REPLACE /ALIGN ALL PARTS INTO PORSITION	New	1,100.00	800.00
3	TO SPRAY PAINT	New	1,300.00	1,000.00
Gross Labour Cost (S\$)			2,650.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >