

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21010554/ETF3N2**Date:** 03/01/2022**REFERENCE**

Insured/Claimant: LEE YOON WOON Policy No: MPC21P00191800
Date of Loss: 06/10/2021 Nature of Claim: OD Claim No: DMPC2100354H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW4213L**
Make & Model: TOYOTA PREVIA, 2.4 7-seater (A) Engine No: 2AZH465607
Reg. Date: 23/03/2010 (Man. Year: 2010) Chassis No: JTEGD54M00A019313
Colour: Black Odometer: 163475 km
Engine Capacity: 2362 cc
Market Value/New Car Price: S\$60,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,166.15	6,141.50	1,024.65	14.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	2,130.00	380.00	15.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,676.15	8,271.50	1,404.65	14.52
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	9,676.15	6,600.00	3,076.15	31.79
+ GST 7.00/7.00% (S\$)	677.34	462.00	215.34	31.79
Nett Amount (S\$)	10,353.49	7,062.00	3,291.49	31.79

INSPECTION

Date of Assignment: 13/10/2021 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected: 14/10/2021 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Estimated Period of Repair: 6.0 days Blk 3 Pioneer Road North, #01-18 Singapore 628457

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2022)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW4213L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	35.00 FS	*35.00 FS
2	1		*FRT BUMPER (WCP)	Broken	280.00 F	*280.00 F
3	2		*FRT BUMPER RETAINER (WCP)	Broken	90.00 F	*90.00 F
4	1		*FRT BUMPER LOWER GRILLE (WCP)	Broken	120.00 F	*120.00 F
5	1		*FRT BUMPER SPONGE (WCP)	Crushed	70.00 F	*70.00 F
6	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	150.00 F	*150.00 F
7	2		*FRT BUMPER SIDE GUIDE (WCP)	Not Necessary	90.00 F	*- F
8	1		*FRT BUMPER TOWING COVER LH (WCP)	Missing	25.00 F	*25.00 F
9	2		*FRT FOGLAMP (WCP)	Not Necessary	260.00 F	*- F
10	2		*FRT FOGLAMP INNER BRACKET (WCP)	Not Necessary	110.00 F	*- F
11	1		*FRT GRILLE (WCP)	Broken	240.00 F	*240.00 F
12	1		*FRT GRILLE EMBLEM (WCP)	Cut	45.00 F	*45.00 F
13	1		*FRT GRILLE TOP GARNISH (WCP)	Crushed	150.00 F	*150.00 F
14	10		*FRT GRILLE TOP GARNISH CLIP (WCP)	Necessary	15.00 F	*15.00 F
15	1		*FRT BONNET (WCP)	Dented	240.00 F	*240.00 F
16	2		*FRT BONNET HINGE (WCP)	Bent	80.00 F	*80.00 F
17	1		*FRT BONNET STAND (WCP)	Not Necessary	35.00 F	*- F
18	1		*FRT BONNET STAND CLIP (WCP)	Not Necessary	1.50 F	*- F
19	1		*FRT BONNET SEAL (WCP)	Not Necessary	40.00 F	*- F
20	1		*FRT BONNET INSULATOR (WCP)	Crushed	150.00 F	*150.00 F
21	10		*FRT BONNET INSULATOR CLIP (WCP)	Necessary	15.00 F	*15.00 F
22	1		*FRT BONNET LOCK (WCP)	Bent	55.00 F	*55.00 F
23	1		*FRT FENDER INNERSHIELD 2 Pcs (WCP)	Torn (1 Pc only)	200.00 F	*100.00 F
24	20		*FRT FENDER INNERSHIELD CLIP (WCP)	Necessary	30.00 F	*10.00 F
25	2		*FRT HEADLAMP (WCP)	Broken	800.00 F	*800.00 F
26	1		*FRT UPPER SUPPORT (WCP)	Dented	180.00 F	*180.00 F
27	1		*FRT LOWER SUPPORT (WCP)	Dented	150.00 F	*150.00 F
28	2		*FRT SIDE SUPPORT (WCP)	Bent	300.00 F	*300.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*FRT BRACE PANEL (WCP)	Bent	45.00 F	*45.00 F
30	1		*FRT HORN (WCP)	Not Necessary	65.00 F	*- F
31	1		*AIRCON CONDENSER (WCP)	Dented	480.00 F	*480.00 F
32	1		*AIRCON FAN BLADE (WCP)	Broken	70.00 F	*70.00 F
33	1		*AIRCON FAN MOTOR (WCP)	Jammed	180.00 F	*180.00 F
34	1		*RADIATOR ASSY (WCP)	Bent	580.00 F	*580.00 F
35	1		*RADIATOR FAN MOTOR (WCP)	Jammed	180.00 F	*180.00 F
36	1		*FAN COWLING (WCP)	Broken	120.00 F	*120.00 F
37	1		*AIR INLET CLEANER NO.1 (WCP)	Crushed	70.00 F	*70.00 F
38	1		*AIR INLET CLEANER NO.2 (WCP)	Not Necessary	70.00 F	*- F
39	1		*RESONATOR ASSY (WCP)	Broken	120.00 F	*120.00 F
40	1		*COOLANT	Necessary	40.00 FS	*40.00 FS
41	2		*FRT BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	140.00 F	*- F
<u>Supplementary #1</u>						
42	1		*RADIATOR FAN BLADE (WCP)	Broken	85.00 F	*85.00 F
43	1		*RADIATOR FAN COWLING TOP (WCP)	Broken	85.00 F	*85.00 F
44	1		*BUMPER UNDER COVER (WCP)	Broken	140.00 F	*140.00 F
45	1		*RADIATOR COOLANT PIPE (WCP)	Bent	95.00 F	*95.00 F
F=Franchise part. S=SpcNett.						
					Sub Total (S\$)	6,521.50
					+ Margin on L,N Items 10.00/10.00% (S\$)	644.65
					Total Parts (S\$)	7,166.15
						5,590.00
						6,141.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	30.00
2	TOP UP AIRCON GAS	New	100.00	100.00
3	TO KNOCK FRT FENDER X2, WELD,REMOVE & FIX ON ABOVE PARTS	New	1,200.00	1,000.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	1,000.00
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00	0.00
Gross Labour Cost (\$\$)			2,510.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >