

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21010557/TEA3Q2**Date:** 20/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLW1116E **Insured Vehicle No :** SLN1967M
 Date of Loss: 09/10/2021 Nature of Claim: TP Claim No: MFL2021D0004411

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW1116E**
 Make & Model: TOYOTA HARRIER, 2.0 ELEGANCE CVT (A) Engine No: 3ZRB896069
 Reg. Date: 24/04/2017 (Man. Year: 2016) Chassis No: ZSU600090509
 Colour: White Odometer: 84665 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,439.27	10,394.52	12,044.75	53.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,180.00	2,820.00	3,360.00	54.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,619.27	13,214.52	15,404.75	53.83
Approved Total (Overridden) (S\$)		10,500.00		
(S\$)	28,619.27	10,500.00	18,119.27	63.31
+ GST 7.00/7.00% (S\$)	2,003.35	735.00	1,268.35	63.31
Nett Amount (S\$)	30,622.62	11,235.00	19,387.62	63.31
+ Car Rental (7.0 x S\$150.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,292.45		
Global Sum Settlement (S\$)		10,500.00		

INSPECTION

Date of Assignment: 13/10/2021
 Date Inspected: 15/10/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW1116E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,489.00 FL	*1,369.50 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
3	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	50.00 FL	*50.00 FL
4	1		*TAILGATE BADGE	Necessary	60.50 FL	*60.50 FL
5	1		*TAILGATE EMBLEM (HARRIER)	Necessary	89.00 FL	*89.00 FL
6	1		*TAILGATE EMBLEM (TURBO)	Necessary	95.00 FL	*95.00 FL
7	1		*TAILGATE OUTER GARNISH	Not Necessary	512.00 FL	*- FL
8	1		*TAILGATE OUTER GARNISH MULDING	Not Necessary	245.00 FL	*- FL
9	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	316.00 FL	*- FL
10	1		*TAILGATE OPENER SWICTH	Not Necessary	217.90 FL	*- FL
11	1		*TAILGATE INNER WARNING COVER	Not Necessary	85.00 FL	*- FL
12	2		*TAILGATE LAMP	Necessary	928.60 FL	*845.60 FL
13	1		*TAILGATE INNER TRIM	Cracked	477.60 FL	*389.00 FL
14	2		*TAILGATE POCKER HANDLE	Missing	197.20 FL	*197.20 FL
15	1		*TAILGATE INNER LOCK MOTOR	Bent	665.00 FL	*355.50 FL
16	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Cut	298.40 FL	*298.40 FL
18	1		*TAILGATE LOCK DETECTOR	Cracked	317.90 FL	*217.00 FL
19	1		*TAILGATE LOCK DETECTOR WIRE HARNESS	Cut	689.00 FL	*489.00 FL
20	2		*TAILGATE HINGE	Not Necessary	218.00 FL	*- FL
21	2		*TAILGATE ABSORBER	Not Necessary	422.00 FL	*- FL
22	2		*TAIL LAMP	Cracked	1,378.00 FL	*961.20 FL
23	2		*TAIL LAMP LOWER BRACKET	Cracked	170.00 FL	*170.00 FL
24	2		*REAR BUMPER SIDE RETAINER	Deformed	240.00 FL	*120.00 FL
25	1		*REAR BUMPER SPONGE	Not Necessary	317.50 FL	*- FL
26	2		*REAR BUMPER REFLECTOR	Cut	355.80 FL	*240.00 FL
27	1		*END PANEL	Bent	861.10 FL	*715.00 FL
28	1		*END PANEL TOP TRIM	Deformed	288.70 FL	*277.80 FL
29	1		*REAR FLOOR PANEL	Repair	1,254.00 FL	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD OUTER	Deformed	689.00 FL	*589.00 FL
31	1		*REAR FLOOR PANEL TOP BOARD INNER	Deformed	689.00 FL	*389.00 FL
32	1		*REAR FLOOR PANEL CENTER TOOL BOX	Cracked	411.10 FL	*211.00 FL
33	1		*REAR FLOOR PANEL SIDE TOOL BOX LH	Cracked	354.00 FL	*175.00 FL
34	1		*REAR FLOOR PANEL SIDE TOOL BOX RH	Cracked	331.00 FL	*175.00 FL
35	2		*REAR FENDER INNER TRIM	Cracked	1,970.00 FL	*1,193.60 FL
36	2		*REAR FENDER INNER SHIELD	Torn	397.40 FL	*397.40 FL
37	1		*REAR EXHAUST SILENCER	Repair	1,242.00 FL	*- FL
38	2		*REAR EXHAUST MOUNTING	Not Necessary	100.00 FL	*- FL
39	1		*REAR EXHAUST GASKET	Not Necessary	45.00 FL	*- FL
40	1		*REAR EXHAUST HEAT PLATE	Not Necessary	217.00 FL	*- FL
41	1		*CENTER PILLAR INNER TRIM	Not Necessary	458.00 FL	*- FL
42	1		*SEAT BELT	Activated	985.00 FL	*565.00 FL
43	1		*SRS AIRBGA ECU	Not Necessary	1,455.00 FL	*- FL
44	1		*REAR BUMPER BODY KIT	Cracked	3,000.00 FS	*1,500.00 FS
45	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
46	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*20.00 FS
48	1		*TAILGATE EMBLEM (TURBO)	Not Necessary	200.00 FS	*- FS
49	1		*TAILGATE SIDE RUBBER SEAL	Not Necessary	250.00 FS	*- FS
50	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
52	1		*REAR BUMPER CENTER LAMP	Cracked	350.00 FS	*100.00 FS
53	1		*REAR BUMPER STEP PLATE	Bent	300.00 FS	*150.00 FS
54	1		*SET REAR BUMPER GRILLE	Necessary	300.00 FS	*100.00 FS
55	1		*END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
56	1		*END PANEL TOP TRIM CLIP	Necessary	30.00 FS	*10.00 FS
57	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
59	1		*REAR FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*20.00 FS
60	1		*REVERSE SENSOR	Not Working	450.00 FS	*200.00 FS
61	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,895.70	13,102.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,456.43	2,708.18
Total Parts (\$\$)	22,439.27	10,394.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,200.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	30.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	120.00
6	REMOVE AND INSTALL TAIL GATE MECHANISM AND PART	New	150.00	60.00
7	REMOVE INSTALL AND CHECK REVERSE SENSOR	New	150.00	30.00
8	REMOVE INSTALL AND CHECK REVERSE CAMERA	New	200.00	30.00
9	REMOVE AND INSTALL CARPET TRIM AND INTERIOR SEAT ,ROOF TOP MAP	New	600.00	60.00
10	REMOVE AND INSTALL REAR EXHAUST	New	150.00	60.00
11	REAR CHASSIS ALIGNMENT	New	680.00	0.00
12	SRS AIR BAG RESET	New	600.00	200.00
Gross Labour Cost (\$\$)			6,180.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >