

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21010559/DPA3Q2

Date:

14/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800055340

Claimant Vehicle No : SMC7075T**Insured Vehicle No :**

SJV6766A

Date of Loss: 10/10/2021

Nature of Claim:

TP

Claim No:

5467256662SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMC7075T**

Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)

Engine No:

FB20YE24718

Reg. Date: 18/07/2018 (Man. Year: 2018)

Chassis No:

JF1SJ5KC5JG111292

Colour: Brown

Odometer:

42550 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size:

225/60 R17

Front Left Side: Yokohama 5 mm

Rear Left Side:

Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,257.30	4,129.44	5,127.86	55.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,990.00	2,010.00	50.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,257.30	6,119.44	7,137.86	53.84
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		

Nett Liability (S\$)	7,326.89
Global Sum Settlement (S\$)	7,300.00

INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	14/10/2021	Inspected At:	Goh Lee Hwa Automobile Pte Ltd BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536
Estimated Period of Repair:	6.0 days		

Adjuster:	BRYAN TANI	Manager:	CHEW HSIAO TONG
------------------	------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	598.00 F	*- FN
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	26.20 F	*- FN
3	10		*FRONT BUMPER CLIPS	Serviceable	30.00 F	*- FN
4	1		*FRONT RH FENDER	Dented	292.00 F	*292.00 FN
5	1		*FRONT RH FENDER LOWER PAD	Cut / Mtg Cracked	28.00 F	*28.00 FN
6	1		*FRONT RH FENDER DUST GARNISH	Serviceable	119.00 F	*- FN
7	10		*FRONT RH FENDER DUST GARNISH CLIPS	Not Necessary	28.00 F	*- FN
8	1		*FRONT RH DOOR SIDE MIRROR ASSY	Not Necessary	869.00 F	*- FN
9	1		*FRONT RH DOOR	Dented	731.00 F	*504.00 FN
10	1		*FRONT RH DOOR LOWER GARNISH	Cut	199.00 F	*199.00 FN
11	1		*FRONT RH DOOR LOWER GARNISH CLIPS (8 PCS)	Necessary	22.40 FS	*15.00 FS
12	1		*REAR RH DOOR	Dented	695.00 F	*495.00 FN
13	1		*REAR RH DOOR LOWER GARNISH	Cut	155.00 F	*155.00 FN
14	1		*REAR RH DOOR GARNISH CLIPS (8 PCS)	Necessary	15.20 FS	*15.00 FS
15	2		*SPORT RIM (O/S FRONT & O/S REAR)	Cut	1,960.00 F	*1,960.00 FN
16	2		*TYRE	Not Necessary	798.00 F	*- FN
17	1		*STEERING TIE ROD RH	Bent	299.00 F	*219.00 FN
18	1		*STEERING TIE ROD END RH	Distorted	165.00 F	*165.00 FN
19	1		*KNUCKLE ARM	Distorted	498.00 F	*377.30 FN
20	1		*KNUCKLE HUP	Not Necessary	385.00 F	*- FN
21	1		*KNUCKLE WHEEL BEARING	Damaged	290.00 F	*167.00 FN
22	1		*LOWER ARM	Not Necessary	410.00 F	*- FN
23	1		*RH WHEEL CAP	Cut	45.00 F	*45.00 FN
24	1		*RH REAR FENDER RUBBER	Cut	117.50 F	*55.00 FN
25	1		*SET FRONT DOOR CHANNEL TAPE	Necessary	80.00 FS	*60.00 FS
26	1		*SET REAR DOOR CHANNEL TAPE	Necessary	89.00 FS	*60.00 FS
27	1		*FRONT DOOR INNER RUBBER	Necessary	158.00 F	*158.00 FN
28	1		*REAR DOOR INNER RUBBER	Necessary	155.00 F	*155.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	9,257.30	5,124.30
- Nett Item Discount on N Items 0.00/20.00% (\$)	0.00	994.86
Total Parts (\$)	9,257.30	4,129.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT WIRING & CHECK ALL WIRING SYSTEM	New	180.00	0.00
2	TO REMOVE & REFIT SPORTS RIM & BALANCING TYRE	New	100.00	50.00
3	TO REMOVE & REFIT INTERIOR GARNISH DOOR BOARD	New	160.00	120.00
4	TO KNOCKING STRAIGHTENING REPAIR & NEW ALL ACCIDENT AFFECTED AREA	New	1,200.00	700.00
5	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED DAMAGE PARTS	New	1,500.00	900.00
6	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	180.00	40.00
7	TO CHECK COMPUTER WHEEL ALIGNMENT ADJUST CAMBER CASTOR ,AND TEST DRIVE	New	180.00	60.00
8	TO REMOVE & RENEW ,REPAIR UNDERCARRIAGE AFFECTED DAMAGE PARTS	New	500.00	120.00
Gross Labour Cost (S\$)			4,000.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >