



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 6964U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR RH TAIL LAMP	SERVICEABLE	365.10	-
1	REAR RH CORNER PANEL	TO REPAIR SEE LABOUR	376.50	-
1	REAR RH CORNER PANEL BRACKET	NOT NECESSARY	31.50	-
1	REAR BUMPER	CUT / TORN	496.40	496.40
1	REAR BUMPER BRACKET O/S	CRACKED	202.00	98.10
	LESS 25% DISCOUNT		-	-148.63
			1,471.50	445.87
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	REAR "CORPORATE" ADVERTISEMENT & ARTWORK STICKER (SN)	NECESSARY	200.00	120.00
			248.00	168.00
	<b><u>LABOUR</u></b>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		30.00	20.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF REAR RH CORNER PANEL.		500.00	250.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		500.00	400.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	30.00	-
			1,060.00	670.00
	<b>GRAND TOTAL</b>		<b>2,779.50</b>	<b>1,283.87</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,000.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/SMR21010566/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.