

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                |       |                       |  |
|---|---|---|----------------|-------|-----------------------|--|
|   | STRIDES AUTOMO  | OTIVE SERVICES PTE LTD  |                | Ref:  | CS/SMR21010566/Uuf3n2 |  |
|   | 60 WOODLANDS I<br>E4SINGAPORE 75  | NDUSTRIAL PARK<br>7705  |                | Date: | 18/10/2021            |  |
|   |   |   |                | Code: | SMR                   |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |   |                |       |                       |  |
|   | Insured Veh.  | SHB 5576S   | Veh. Inspected | t     | GBB 6964U             |  |
|   | Policy No.  |   | Coverage (\$)  |       | 0.00                  |  |
|   | Claim No.   | TAX/10/21/2016  | Excess (\$)    |       | 0.00                  |  |
|   | Assign From   | HUA YEN   | Assign Date    |       | 14/10/2021            |  |
| 2.  | 2. Vehicle Particulars & Condition  |   |                |       |                       |  |
|   | Make & Model  | TOYOTA HIACE (M)  | c.c            |       | 2982                  |  |
|   | Engine No.  | HIDDEN  | Year of Reg.   |       | 2009                  |  |
|   | Chassis No.   | JTFHT02P200047235   | Colour         |       | BLUE                  |  |
|   | Odometer  | 366531 KM   | Steering       |       | IN ORDER              |  |
|   | Brakes  | IN ORDER  | Modification   |       | NIL                   |  |
|   | General   | GOOD  |                |       |                       |  |
| 3. Conditions of Tyres  |   |   |                |       |                       |  |
|   |   | Size  | Make           |       | Balance               |  |
|   | R/H Front Tyre  | 195 R15   | AUSTONE        |       | 6 mm                  |  |
|   | L/H Front Tyre  | 195 R15   | AUSTONE        |       | 6 mm                  |  |
|   | R/H Rear Tyre   | 195 R15   | AUSTONE        |       | 6 mm                  |  |
|   | L/H Rear Tyre   | 195 R15   | AUSTONE        |       | 6 mm                  |  |
| 4.  | 4. Description of Damages   |   |                |       |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  |   |                |       |                       |  |
|   | DAMAGES SEE DETAILS.  |   |                |       |                       |  |
| 5.  | General Information   |   |                |       |                       |  |
|   | Accident Date   | 08/10/2021  | Inspection Da  | te    | 13/10/2021            |  |
|   | Survey held at  | LIU'S BROTHER AUTO ENGINE   | ERING WORKSH   | IOP   |                       |  |
|   |   | 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                |       |                       |  |
| 5a.   | Remarks   |   |                |       |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                |       |                       |  |
| 5b.   | Estimate Days of Repair   |   |                |       |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days  |   |                |       |                       |  |
|   |   |   |                |       |                       |  |