

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010572/VUF3E2

Date: 03/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070059807
Claimant Vehicle No :	FBS7345K	Insured Vehicle No :	SMT2773E
Date of Loss:	10/10/2021	Nature of Claim:	TP
		Claim No:	3980241366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS7345K	Engine No:	G3L8E0556653
Make & Model:	YAMAHA NMAX155, 155cc ABS CVT	Chassis No:	MH3SG5680MJ079379
Reg. Date:	26/07/2021 (Man. Year: 2021)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	110/70 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/10/2021		
Date Inspected:	14/10/2021	Inspected At:	M1 Motoring (HQ) 411 Changi Road Singapore 419860
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$13,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
4	1		*FRONT WINDSHIELD	Distorted	0.00 F	*- F
5	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
6	1		*CLUTCH LEVER	Cut	0.00 F	*- F
7	1		*SIDE FAIRING	Distorted	0.00 F	*- F
8	1		*SIDE FAIRING TOP GARNISH	Scratched	0.00 F	*- F
9	1		*REAR BOX	Cut	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >