12/13/21, 11:43 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010575/ETY3N2

13/12/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00108892104

Claimant Vehicle

YP4023C

Insured Vehicle No:

YN6495X

No:

Nature of

Date of Loss:

13/10/2021

TP Claim:

Claim

SNM21D205840/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

YP4023C Reg No:

MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) Make & Model:

Engine No: 4P10C25690

Reg. Date: 06/09/2016 (Man. Year: 2016)

Chassis No: Odometer:

FEB71EA20229 244647 km

Colour: White **Engine Capacity:** 2998 cc

N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/75R17.5 215/75R17.5 Rear Tyre Size: Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm Front Right Side: Rear Right Side: Bridgestone 4 mm Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,721.00	4,453.30	1,267.70	22.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,250.00	550.00	30.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,521.00	5,703.30	1,817.70	24.17
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	7,521.00	4,550.00	2,971.00	39.50
+ GST 7.00/7.00% (S\$)	526.47	318.50	207.97	39.50
Nett Amount (S\$)	8,047.47	4,868.50	3,178.97	39.50

INSPECTION

Date of Assignment: 15/10/2021

Connect3 (HQ)

Date Inspected: 15/10/2021 566 Woodlands Road Singapore 728697

Estimated Period of Repair: 5.0 days

DENISE TAY KWEE CHENG Adjuster: **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Dec 2021)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP4023C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER CENTER	Dented	1,010.00 F	*1,010.00 FL
2	1		*FRONT GRILLE	Broken	1,105.00 F	*994.00 FL
3	1		*MIT EMBLEM	Necessary	96.00 F	*96.00 FL
4	1		*FUSO LOGO	Necessary	375.00 F	*375.00 FL
5	1		*CENTER LOGO	Necessary	75.00 F	*75.00 FL
6	1		*FRONT PANEL	Dented	2,436.00 F	*2,337.00 FL
7	1		*FRONT GRILLE GARNISH	Not Necessary	544.00 F	*- FL
8	5		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*15.00 FS
9 E-Er	1	nart S-SncNe	*FRONT NUMBER PLATE tt. L=ListItemDisc.	Bent	50.00 FS	*40.00 FS
1 -1 16	ai ici iise	part. 0-opcive	u. L-Listitembisc.	Sub Total (S\$)	5,721.00	4,942.00
			- List Item Discou	0.00	488.70	
				Total Parts (S\$)	5,721.00	4,453.30
			Report was unsu	Ibmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES	New	900.00	800.00
2	SPRAY PAINTING	New	900.00	450.00
		Gross Labour Cost (S\$)	1,800.00	1,250.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >