12/17/21, 11:42 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010576/AVY3N2

Date: 17/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00078882103

Claimant Vehicle

SLP8158A

Insured Vehicle No :

GBH6326E

Date of Loss:

No:

04/10/2021

Nature of Claim: TP

Clain

SNM21D205848/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP8158A

Make & Model: LEXUS UX250H, 2.0 (A) Engine No:

Engine No: M20AN293775

Reg. Date: 23/04/2021 (Man. Year: 2021)

Chassis No: Odometer:

JTHY65BH002094563

Yes

8655 km

Colour: Black Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18 Rear Tyre Size: 225/50R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,475.70	4,305.20	170.50	3.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,215.00	780.00	1,435.00	64.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,690.70	5,085.20	1,605.50	24.00
+ GST 7.00/7.00% (S\$)	468.35	355.96	112.39	24.00
Nett Amount (S\$)	7,159.05	5,441.16	1,717.89	24.00

INSPECTION

Date of Assignment: 15/10/2021

23 KAKI BUKIT AVE 4 # 03-01

Date Inspected: 13/10/2021 Inspected At: SINGAPORE 415933

REPAIRER: SK AUTOMOBILE PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

\sim	_	_	_	_
$\boldsymbol{\omega}$		T 1		_
u			U	
	e	ere	eren	erence

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Dec 2021)

Parts: M1-SUV LEXUS UX250H 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP8158A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cut	3,934.00 FL	*3,934.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	45.00 FL	*- FL
3	1		*FRONT BUMPER RH	Deformed	345.00 FL	*345.00 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	80.00 FL	*80.00 FL
5	1		*FRONT FENDER ARCH GARNISH RH	Cut	369.00 FL	*369.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
7	1		*FRONT FENDER ARCH GARNISH CLIPS SET RH	Necessary	40.00 FS	*20.00 FS
8	1		*FRONT FENDER INNER SHIELD CLIPS SET RH	Not Necessary	60.00 FS	*- FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,953.00	4,778.00
			- List Item Discount on L Items 10.00/10.00% (S\$)		477.30	472.80
				Total Parts (S\$)	4,475.70	4,305.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	750.00	300.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	750.00	200.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	75.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	180.00	50.00
6	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	200.00
	Gross Labour Cost (S\$)		2,215.00	780.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >