

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010578/EQY3N2**Date:** 09/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00005462101

Claimant Vehicle No : SHA8117U **Insured Vehicle No :** SMQ7274L

Date of Loss: 13/10/2021 Nature of Claim: TP Claim No: SNM21D205854/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA8117U**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Engine No: G4LEKU391347

Reg. Date: 29/01/2021 (Man. Year: 2019) Chassis No: KMHC851CVLU184830

Colour: Yellow Odometer: 51229 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Sailun 5 mm Rear Left Side: Sailun 5 mm

Front Right Side: Sailun 5 mm Rear Right Side: Sailun 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,708.33	1,755.88	1,952.45	52.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	510.00	1,190.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	5,408.33	2,265.88	3,142.45	58.10

INSPECTION

Date of Assignment: 20/10/2021

Date Inspected: 14/10/2021 Inspected At: Ding Auto Pte Ltd (corporation Road) (HQ)
31 Corporation Road
Singapore 649825

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2021)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8117U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR LH DOOR PANEL	Dented	2,256.30 FL	*1,789.90 FL
2	1	*REAR LH DOOR FRAME UPPER BLACK TAPE	Necessary	9.70 FL	*9.70 FL
3	1	*REAR LH DOOR FRAME REAR BLACK TAPE	Necessary	7.00 FL	*7.00 FL
4	1	*REAR LH DOOR FRAME FRONT BLACK TAPE	Necessary	7.00 FL	*7.00 FL
5	1	*REAR LH OUTER DOOR HANDLE	Cut	189.60 FL	*189.60 FL
6	1	*REAR LH OUTER DOOR HANDLE COVER	Not Necessary	21.10 FL	*- FL
7	1	*REAR LH OUTER DOOR HANDLE BASE	Not Necessary	40.90 FL	*- FL
8	1	*REAR LH DOOR MODULE PANEL ASSY	Not Necessary	350.22 FL	*- FL
9	1	*REAR LH POWER WINDOW REGULATOR MOTOR	Not Necessary	785.85 FL	*- FL
10	1	*REAR LH DOOR DIVISION BAR ASSY	Not Necessary	53.30 FL	*- FL
11	1	*REAR LH OUTER DOOR BELT MOULDING	Not Necessary	74.90 FL	*- FL
12	1	*REAR LH DOOR LOCK	Not Necessary	240.54 FL	*- FL
13	1	*REAR LH REAR DOOR DIVISION BAR CHANNEL RUN	Not Necessary	28.00 FL	*- FL
14	1	*REAR LH DOOR GLASS RUN	Not Necessary	73.10 FL	*- FL
15	1	*REAR LH OUTER DOOR HANDLE FRONT PAD	Necessary	5.20 FL	*5.20 FL
16	1	*REAR LH OUTER DOOR HANDLE REAR PAD	Necessary	5.20 FL	*5.20 FL
17	1	*REAR DOOR COMFORT DELGRO STICKER	Necessary	140.00 FS	*80.00 FS
18	1	*REAR DOOR *GOOGLE PLAY STORE *APP STORE* STICKER	Necessary	140.00 FS	*50.00 FS
19	1	*SET DOOR MOULDING CLIP	Necessary	55.00 FS	*15.00 FS
20	1	*SET DOOR TRIM BOARD CLIP	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,537.91	2,158.60
- List Item Discount on L Items 20.00/20.00% (\$)	829.58	402.72
Total Parts (\$)	3,708.33	1,755.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	New	800.00	200.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO TRANSFER OF REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	New	220.00	50.00
4	TO DIAGNOSTIC,CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	260.00	30.00
5	TO RESPRAY REAR DOOR PANEL	New	250.00	200.00
Gross Labour Cost (\$\$)			1,700.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >