

YAP LEE MOTOR

NO 1 KAKI BUKIT AVENUE 6 #01-26
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6844 1555

Vehicle No: SLC319Z

Date: 15/10/2021

Make/Model: Mercedes CLA180

TP AXA

Veron.

WDD1179422N222855

ESTIMATE COST OF REPAIRS FOR Toyota Wish SML6921K

Qty Descriptions List Item

Amount

1 Bootlid	\$ 2,275.00	x
1 Bootlid Locks	\$ 398.00	x
1 Bootlid Lock Catch	\$ 181.00	x
1 Bootlid Weatherstrip	\$ 297.00	x
2 Botlid Hinge	\$ 620.00	x
1 Bootlid "C&C" Emblem	\$ 89.00	x
1 Bootlid Mercedes-Benz Logo	\$ 118.00	x
1 Bootlid "CLA180" Emblem	\$ 106.00	x
1 Bootlid Inner Trim	\$ 328.00	x
1 End Panel	\$ 957.00	x
1 End Panel Top Garnish	\$ 223.00	x
1 Rear Compartment Top Board	\$ 423.00	+
2 Tail Lamp	\$ 1,908.00	954.750
2 Tail Lamp Panel	\$ 482.00	x
1 Rear Bumper	\$ 2,095.00	1438
1 Rear Bumper Diffuser	\$ 1,244.00	695
1 Rear Bumper Lower Cowling	\$ 368.00	-
1 Rear Bumper Tow Hook Cover	\$ 59.00	-
2 Rear Bumper Side Retainer	\$ 298.00	105
1 Rear Bumper Reinforcement	\$ 915.00	585
2 Rear Bumper Reinforcement Bracket	\$ 422.00	x
1 Rear Bumper Center Bracket	\$ 343.00	-
4 Reverse Sensor	\$ 1,520.00	520
1 Rear Exhaust Pipe	\$ 1,180.00	✓

Less 5%

\$ 16,849.00
\$ 842.45
\$ 16,006.55

Special Nett Item

1 Bootlid Inner Trim Clip (1 Set)	\$ 60.00	+
1 Rear Bumper Clip (1 Set)	\$ 60.00	-30
1 Rear Number Plate & Frame	\$ 60.00	+
\$ 180.00		

Labour cost

1 To check wiring system	\$ 120.00	30
2 To apply undercoat	\$ 120.00	50
3 To transfer bootlid mechanism	\$ 200.00	x
4 To remove & Refix fender innertrim	\$ 200.00	x
5 To reset auto lock mechanism	\$ 200.00	x
6 To Panel Beat	\$ 1,400.00	600
7 To Spray Paint on affected areas	\$ 1,200.00	600
8 To Remove & Refix exhaust system	\$ 250.00	80
\$ 3,690.00		

GRAND TOTAL

\$19,876.55

20,579.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6043

5438.70

30

1340

Adrian L

1/5 15/10/21

06 Days 06 Days

Supplementary: 490.50

total 7299.20

1/5: 5.8K

YAP LEE MOTOR

NO 1 KAKI BUKIT AVENUE 6 #01-26
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6844 1555

Vehicle No: SLC319Z

Date: 15/10/2021

Make/Model: Mercedes CLA180

ESTIMATE COST OF REPAIRS (Supplementary items)

<u>Qty</u>	<u>Descriptions</u> <u>List Item</u>	<u>Amount</u>
1	Exhaust Chrome Pipe <i>Dented</i>	\$ 360.00 <i>265</i>
1	Rear Bumper Lower Cover <i>torn</i>	280.00 ✓
1	Taillamp Lower Garnish RH <i>XL MR</i>	100.00 X
		\$ 740.00
	Less 5%	\$ 37.00
		\$ 703.00
	GRAND TOTAL	<u>\$703.00</u>

545

Supplementary: 490.50.