

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21010586/Kty3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	17/01/2022	
	ATTN: TEO KITTY			Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7240S	Veh. Inspected	ł	SMH 4183H
	Policy No.	VFX/P2419140	Coverage (\$)		0.00
	Claim No.	S1M03JVN	Excess (\$)		0.00
	Assign From	TEO KITTY	Assign Date		14/10/2021
2. Vehicle Particulars & Condition					
	Make & Model	HONDA JAZZ (A)	c.c		1318
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	JHMGK3850KS200226	Colour		METALLIC GREY
	Odometer	34680 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	175/65 R15	YOKOHAMA		9 mm
	L/H Front Tyre	175/65 R15	YOKOHAMA		9 mm
	R/H Rear Tyre	175/65 R15	DUNLOP		8 mm
	L/H Rear Tyre	175/65 R15	DUNLOP		8 mm
4. Description of Damages					
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY.			
5.	General Information				
	Accident Date	12/10/2021	Inspect Date /	Time	14/10/2021 (02:45 PM)
	Survey held at KUM CHEW MOTOR WORKSHOP				
	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/ASM21010586/Kty3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser