

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21010587/Kqf3e2
	50 RAFFLES PLAC TOWER SINGAPO		Date:	16/11/2021	
				Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLU 8041B	Veh. Inspected	ł	SLU 9717D
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD2102879/LOR	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		14/10/2021
2.	Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E 250 (A)	c.c		1796
	Engine No.	HIDDEN	Year of Reg.		2013
	Chassis No.	WDD2120472A660607	Colour		METALLIC DARK GREEN
	Odometer	141300 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/35 R19	GOODYEAR		8 mm
	L/H Front Tyre	245/35 R19	GOODYEAR		8 mm
	R/H Rear Tyre	245/35 R19	YOKOHAMA		7 mm
	L/H Rear Tyre	245/35 R19	YOKOHAMA		7 mm
4.	Description of Damages				
	THE VEHICLE SUS	E SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	25/09/2021	Inspect Date /	Time	08/11/2021 (10:55 AM)
	Survey held at MJE MOTOR				
	BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/SMO21010587/Kqf3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

DECD Anto Consultant OAE Lineard Assession

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$