LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010589/R1UF3E2

Date: 21/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100026035

Claimant Vehicle

FDD00055

No: FBD9895E Insured Vehicle No: SGV3381G

Date of Loss: 27/04/2021 Nature of Claim: TP Claim No: 2184760495SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBD9895E

Make & Model: YAMAHA YBR125, 124cc (M) Engine No: E3D6E003033

Reg. Date: 14/10/2009 (Man. Year: 2009) Chassis No: LBPKE128690020953

Colour: Red Odometer: 21570 km

Engine Capacity: 124 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-18 Rear Tyre Size: 3.60-18

Front Left Side: Golden Boy 3 mm Rear Left Side: Golden Boy 3 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/10/2021

THCYCLE PTE LTD (HQ)

Date Inspected: 14/10/2021 Inspected At: 61 WOODLANDS INDUCTRIAL PARK E9 #01-04

Singapore 757047

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$7,000.00 (EST)

REPAIR DETAILS

Recommended Parts

} '	1 1 1	*FRONT RIM	Bent	0.005	
}	•	*FDONT FENDED WHEEL CHARD	-	0.00 F	*- F
	1	*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
		*FRONT BRAKE DISC	Scratched	0.00 F	*- F
	1	*FRONT BRAKE CALIPER	Scratched	0.00 F	*- F
,	1	*FRONT FORK ASSY	Bent	0.00 F	*- F
; 1	1	*FRONT FORK REFLECTOR	Scratched	0.00 F	*- F
, ,	1	*FRONT HEADLAMP	Missing	0.00 F	*- F
} ^	1	*FRONT HEADLAMP BRACKET	Bent	0.00 F	*- F
,	1	*METER ASSY	Cracked	0.00 F	*- F
0 ′	1	*HANDLE BAR	Bent	0.00 F	*- F
1 1	1	*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
2 ′	1	*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
3	1	*FUEL TANK	Bent	0.00 F	*- F
4	1	*REAR FAIRING	Scratched	0.00 F	*- F
5 ′	1	*FOOT BRAKE	Scratched	0.00 F	*- F
6	1	*FRONT FOOT REST	Scratched	0.00 F	*- F
7 ′	1	*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
8 ′	1	*REAR FOOT REST	Scratched	0.00 F	*- F
9 ′	1	*REAR FOOT REST BRACKET	Scratched	0.00 F	*- F
20 1	1	*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
21 ′	1	*REAR LH SIGNAL LAMP	Scratched	0.00 F	*- F
22	1	*SIDE BAG RH	Torn	0.00 F	*- F
23 ^	1	*REAR BOX	Missing	0.00 F	*- F
24	1	*REAR BOX BRACKET	Cracked	0.00 F	*- F
=Fran	chise part.		_		
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted do	uring this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >