

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010591/EQY3E2

Date: 20/12/2021

REFERENCE

Insured/Claimant:	TRIN LYOVARIN	Policy No:	2070129233	
Date of Loss:	09/10/2021	Nature of Claim:	OD	Claim No: 4757766215SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS9687R		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM024293
Reg. Date:	12/09/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF40LN015338
Colour:	White	Odometer:	23087 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,320.00	18,187.84	29,132.16	61.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,094.00	11,264.00	6,830.00	37.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	65,414.00	29,451.84	35,962.16	54.98
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	64,314.00	28,351.84	35,962.16	55.92
+ GST 7.00/7.00% (S\$)	4,501.98	1,984.63	2,517.35	55.92
Nett Amount (S\$)	68,815.98	30,336.47	38,479.51	55.92

INSPECTION

Date of Assignment:	14/10/2021		
Date Inspected:	13/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,233.00 FS	*1,786.40 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	358.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP (2PCS)	Missing(1Pc Only)	71.00 FS	*28.16 FS
4	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	262.00 FS	*209.20 FS
6	1	*FRONT BUMPER AIR GUIDE - LH	Broken	44.00 FS	*35.12 FS
7	1	*RADIATOR GRILLE CLOSING ELEMENT - UPPER CENTRE	Not Necessary	262.00 FS	*- FS
8	1	*FRONT BUMPER AIR GRILLE - LH	Missing	135.00 FS	*108.00 FS
9	1	*FRONT BUMPER AIR GRILLE TRIM - LH	Cut	48.00 FS	*38.00 FS
10	1	*RADIATOR GRILLE	Not Necessary	1,580.00 FS	*- FS
11	1	*FRONT BUMPER FOAM PIECE	Not Necessary	189.00 FS	*- FS
12	1	*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
13	1	*FRONT BUMPER GUIDE SECTION - LH	Missing	36.00 FS	*28.72 FS
14	1	*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1	*A/C STICKER	Not Necessary	8.00 FS	*- FS
16	1	*LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
17	2	*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
18	4	*FRONT BUMPER RIVET	Necessary	4.00 FS	*2.56 FS
19	2	*FRONT BUMPER PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
20	4	*FRONT BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
21	1	*HORN - LH	Not Necessary	126.00 FS	*- FS
22	1	*HORN BRACKET - LH	Not Necessary	29.00 FS	*- FS
23	1	*FRONT FENDER - LH	Dented	1,092.00 FS	*873.60 FS
24	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
25	1	*FRONT FENDER CLOSING ELEMENT	Bent	72.00 FS	*57.52 FS
26	2	*FRONT FENDER BRACKET - LH	Bent	67.00 FS	*53.04 FS
27	1	*FRONT FENDER DEFORMATION BRACKET - LH	Bent	49.00 FS	*39.20 FS
28	1	*FRONT FENDER BRACE - LH	Bent	118.00 FS	*94.40 FS
29	1	*FRONT WHEEL HOUSING LINER - LH	Torn	236.00 FS	*188.80 FS
30	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
31	1	*FRONT WHEEL SPOILER - LH	Broken	73.00 FS	*58.40 FS
32	1	*FRONT WHEEL SPOILER TRIM - LH	Missing	35.00 FS	*27.76 FS
33	1	*FRONT FENDER TOP COVER - LH	Necessary	31.00 FS	*24.64 FS
34	1	*HEADLIGHT TOP COVER - LH	Necessary	44.00 FS	*34.48 FS
35	1	*FRONT FENDER LEDGE COVER - LH	Not Necessary	62.00 FS	*- FS
36	1	*BONNET	Dented	3,246.00 FS	*2,596.80 FS
37	1	*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
38	1	*BONNET IMPACT PROTECTION - LH / RH / CENTER (3PCS)	Necessary	84.00 FS	*65.68 FS
39	1	*BONNET STRIKER - LH	Not Necessary	50.00 FS	*- FS
40	1	*BONNET LOCK	Not Necessary	214.00 FS	*- FS
41	1	*HEADLIGHT - LH	Broken	7,685.00 FS	*6,148.00 FS
42	1	*HEADLIGHT HOSE - LH	Not Necessary	36.00 FS	*- FS
43	1	*HEADLIGHT LIFT CYLINDER - LH	Broken	210.00 FS	*167.60 FS
44	1	*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	0.00 FS	*- FS
45	1	*LOCK CARRIER	Broken	1,016.00 FS	*812.80 FS
46	1	*LOCK CARRIER SUPPORT	Broken	38.00 FS	*30.32 FS
47	1	*LOCK CARRIER BRACKET	Not Necessary	19.00 FS	*- FS
48	1	*INTERCOOLER	Dented	587.00 FS	*469.20 FS
49	1	*A/C PRESSURE PIPE - LH	Not Necessary	427.00 FS	*- FS
50	1	*A/C REFRIGERANT LINE (3PCS)	Bent (1Pc Only)	755.00 FS	*133.20 FS
51	1	*A/C CONDENSER	Not Necessary	622.00 FS	*- FS
52	1	*A/C REFRIGERANT PIPE	Bent	523.00 FS	*418.00 FS
53	1	*A/C REFRIGERANT PIPE BRACKET	Necessary	8.00 FS	*5.76 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*RADIATOR	Broken	904.00 FS	*722.80 FS
55	1	*RADIATOR FAN RING	Not Necessary	267.00 FS	*- FS
56	1	*COOLANT (6PCS)	Not Necessary	266.00 FS	*- FS
57	1	*RADIATOR AIR GUIDE - LH / LH OUTER / LOWER	N/S Lower Cut	82.00 FS	*52.32 FS
58	1	*NOISE INSULATION	Broken	572.00 FS	*457.60 FS
59	1	*FRONT TYRE RIM - LH	Not Necessary	1,155.00 FS	*- FS
60	1	*FRONT SUB FRAME	Bent	1,891.00 FS	*1,512.80 FS
61	1	*FRONT SUB FRAME SUPPORT BRACKET - LH	Broken	472.00 FS	*377.60 FS
62	1	*GEARBOX MOUNTING	Not Necessary	212.00 FS	*- FS
63	1	*GEARBOX SUPPORT	Not Necessary	82.00 FS	*- FS
64	1	*ENGINE MOUNTING	Not Necessary	422.00 FS	*- FS
65	1	*ENGINE MOUNTING SUPPORT - LH	Not Necessary	158.00 FS	*- FS
66	1	*ENGINE SUPPORT BEARING - LH	Not Necessary	67.00 FS	*- FS
67	1	*FRONT WISHBONE LINK - LH	Not Necessary	539.00 FS	*- FS
68	1	*FRONT SUSPENSION GUIDE - LH FRONT	Not Necessary	943.00 FS	*- FS
69	1	*FRONT CONTROL ARM - LH UPPER FRONT	Not Necessary	512.00 FS	*- FS
70	1	*FRONT CONTROL ARM - LH UPPER REAR	Not Necessary	512.00 FS	*- FS
71	1	*FRONT WHEEL BEARING HOUSING - LH	Not Necessary	968.00 FS	*- FS
72	1	*SWIVEL JOINT	Not Necessary	193.00 FS	*- FS
73	1	*FRONT WHEEL HUB - LH	Not Necessary	479.00 FS	*- FS
74	1	*FRONT WHEEL BEARING - LH	Not Necessary	246.00 FS	*- FS
75	1	*FRONT SUSPENSION FORKS - LH	Not Necessary	264.00 FS	*- FS
76	1	*FRONT COUPLING ROD - LH	Not Necessary	127.00 FS	*- FS
77	1	*ANTI-ROLL BAR	Bent	433.00 FS	*346.00 FS
78	1	*FRONT ABSORBER - LH	Not Necessary	301.00 FS	*- FS
79	1	*DRIVE SHAFT - LH	Not Necessary	2,650.00 FS	*- FS
80	1	*STEERING SHAFT	Not Necessary	6,787.00 FS	*- FS
81	1	*TIE ROD END	Not Necessary	197.00 FS	*- FS
82	1	*TRACK ROD	Not Necessary	99.00 FS	*- FS
83	1	*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
84	1	*SUNDRIES	Necessary	500.00 FS	*183.36 FS
85	1	*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
86	1	*DRIVE SHAFT HEAT SHEILF - LH	Not Necessary	32.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 47,320.00 18,187.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	2,000.00	2,000.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
5	TO REMOVE AND REINSTALL LHS FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGED AND RENEW IF NECESSARY	New	2,400.00	2,400.00
6	TO DISLodge AND REINSTALL ENGINE AND GEARBOX ASSY TO FACILITATE RENEWAL OF LHS ENGINE CONSOLE AND SUPPORT	New	1,800.00	0.00
7	TO REMOVE AND RENEW LHS AIRCON REFRIGERANT PIPE	New	280.00	280.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
9	TO RESPRAY FRONT BUMPER, LH SFRONT FENDER, BONNET AND LHS FRONT DOOR	New	4,000.00	2,200.00
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	240.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			18,094.00	11,264.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >