

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 2187E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BRAKE LEVER	SCRATCHED	67.00	67.00
1	MOTOVATION SLIDER	SCRATCHED	300.00	200.00
1	HANDLEBAR	BENT	260.00	157.00
1	BAR ENDS	SCRATCHED	50.00	50.00
1	GEAR LEVER	SCRATCHED	80.00	80.00
1	FRONT DISC	BENT	360.00	107.00
	LESS 10% DISCOUNT		-	-66.10
			1,117.00	594.90
	<u>LABOUR</u>			
	TOWING.		60.00	60.00
	LABOUR.		400.00	250.00
			460.00	310.00
	GRAND TOTAL		1,577.00	904.90

RECOMMENDED COST OF LUMP SUM REPAIRS		700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/AIG21000057/R1qy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

XX. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.