

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010593/AGA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210094780
Claimant Vehicle No :	SLH2212H	Insured Vehicle No :	SNB3515K
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	6214935821SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH2212H		
Make & Model:	BMW 428I, 2.0 CONVERTIBLE D/AB HID NAV (A)	Engine No:	A2360774N20B20A
Reg. Date:	14/07/2014 (Man. Year: 2014)	Chassis No:	WBA3V32010J993139
Colour:	Green	Odometer:	92814 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,240.55	8,759.46	9,481.09	51.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,510.00	2,490.00	3,020.00	54.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,750.55	11,249.46	12,501.09	52.63
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	23,750.55	9,000.00	14,750.55	62.11
+ GST 7.00/7.00% (S\$)	1,662.54	630.00	1,032.54	62.11
Nett Amount (S\$)	25,413.09	9,630.00	15,783.09	62.11
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,337.45		

INSPECTION

Date of Assignment:	12/10/2021	MG Solution Pte Ltd (HQ)
Date Inspected:	12/10/2021 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,355.20 FL	*1,858.00 FL
2	1		*BOOT LID LOGO	Necessary	150.00 FL	*150.00 FL
3	1		*BOOT LID 428I EMBLEM	Necessary	80.00 FL	*80.00 FL
4	1		*BOOT LID TOP LOCK	O/S Damaged	844.40 FL	*422.20 FL
5	1		*BOOT LID WEATHERSTRIP	Not Necessary	250.30 FL	*- FL
6	2		*REAR BOOT LID LAMP	Cracked	910.40 FL	*910.40 FL
7	2		*AUTO BOOTLID SENSOR	Not Necessary	461.00 FL	*- FL
8	1		*AUTO BOOTLID SENSOR HOLDER	Cracked	280.32 FL	*280.32 FL
9	1		*AUTO BOOTLID SENSOR MODULE	Not Necessary	520.30 FL	*- FL
10	2		*REAR BOOT LID LAMP	Repeated	910.40 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,855.20 FL	*1,385.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	288.40 FL	*- FL
13	1		*REAR BUMPER CHROME	Cut	580.20 FL	*358.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	855.20 FL	*617.00 FL
15	1		*REAR BUMPER TOW HOOK COVER	Deformed	60.00 FL	*60.00 FL
16	1		*REAR BUMPER REFLECTOR	N/S Cracked	381.00 FL	*131.00 FL
17	1		*REAR BUMPER CENTER BRACKET (CENTER)	Cracked	255.30 FL	*255.30 FL
18	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	1,280.80 FL	*580.00 FL
19	4		*REAR BUMPER SENSOR HOLDER	Necessary	220.80 FL	*80.00 FL
20	4		*REAR BUMPER SENSOR RUBBER	Necessary	160.00 FL	*40.00 FL
21	2		*TAIL LAMP	Cracked	1,310.40 FL	*1,310.40 FL
22	2		*TAIL LAMP LOWER BRACKET	Not Necessary	220.40 FL	*- FL
23	1		*REAR END PANEL	Dented	1,255.20 FL	*806.00 FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	210.50 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	3,800.00 FL	*- FL
26	1		*REAR EXHAUST HEAT SEAL	Not Necessary	218.00 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	298.00 FL	*298.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
30	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
31	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
32	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,241.72	9,721.62
- List Item Discount on L Items 10.00/10.00% (\$)	2,001.17	962.16
Total Parts (\$)	18,240.55	8,759.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	140.00	60.00
6	TRANFER BOOTLID MECHANISM	New	250.00	80.00
7	REMOVE AND REFIX REAR EXHAUST PIPE	New	220.00	0.00
8	TRANSFER BOOTLID CAMERA	New	150.00	60.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	320.00	200.00
Gross Labour Cost (\$\$)			5,510.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >