1/4/22, 2:45 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010594/KVY3N2

04/01/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00031292101

Claimant Vehicle

SLN4990A

Insured

No:

Vehicle No:

XE483D

Date of Loss:

12/10/2021

Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM21D205845/C02/TOHHS

WAUZZZF40HA017945

CVN016665

212635 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLN4990A Reg No:

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

Reg. Date: 25/08/2016 (Man. Year: 2016)

Colour: White

Engine Capacity:

1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16 Front Left Side: Rear Left Side: Michelin 8 mm Toyo 6 mm Front Right Side: Toyo 6 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,956.75	14,022.25	1,934.50	12.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,180.00	1,670.00	58.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,806.75	15,202.25	3,604.50	19.17
Approved Total (Overridden) (S\$)		11,900.00		
(S\$)	18,806.75	11,900.00	6,906.75	36.72
+ GST 7.00/7.00% (S\$)	1,316.47	833.00	483.47	36.72
Nett Amount (S\$)	20,123.22	12,733.00	7,390.22	36.72

INSPECTION

Date of Assignment: 15/10/2021

Thiam Heng Huat Pte Ltd (SIN MING) 14/10/2021 Inspected At: Date Inspected:

176 SIN MING DRIVE, #05-14

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: **KENNETH KONG** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

1/4/22, 2:45 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2022)

Parts: 143 AUDI A4 2.0 TFSI S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN4990A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

Condition

Donairor's

Amount

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Oty Part No Particulars

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,703.00 FL	*1,703.00 FL
2	1		*FRONT BUMPER FIXING PARTS	O/s Cracked	460.00 FL	*230.00 FL
3	1		*FRONT BUMPER AIR GUIDE-RH	Dented	64.00 FL	*64.00 FL
4	1		*FRONT BUMPER GRILLE-RH	Dented	108.00 FL	*108.00 FL
5	1		*FRONT BUMPER REINFORCEMENT BEAM	Repair	630.00 FL	*- FL
6	1		*FRONT BUMPER GUIDE-RH	Serviceable	26.00 FL	*-FL
7	1		*FRONT REINFORCEMENT BEAM HOLDER-RH	Distorted	172.00 FL	*172.00 FL
8	1		*FRONT REINFORCEMENT BEAM BOLT SET	Serviceable	39.00 FL	*-FL
9	1		*FRONT BUMPER INNER FOAM	Cracked	197.00 FL	*197.00 FL
10	1		*FRONT BUMPER TOP COVER	Buckled	104.00 FL	*104.00 FL
11	1		*RADIATOR GRILLE COMPLETE	Cracked	1,202.00 FL	*1,202.00 FL
12	1		*HEADLIGHT WASHER CYLINDER-RH	Cracked	178.00 FL	*178.00 FL
13	1		*BRACKET FOR WASHER CYLINDER-RH	Distorted	9.00 FL	*9.00 FL
14	1		*WASHER HOSE	Serviceable	108.00 FL	*- FL
15	1		*HEADLIGHT WASHER CYLINDER SPRING CLIP	Missing	18.00 FL	*18.00 FL
16	1		*LED HEADLIGHT-RH	Broken	7,803.00 FL	*7,693.00 FL
17	1		*BONNET	Bent	1,867.00 FL	*1,867.00 FL
18	1		*BONNET ATTACHMENT PARTS	Serviceable	124.00 FL	*-FL
19	1		*BONNET STOPPER SET	Serviceable	24.00 FL	*- FL
20	1		*BONNET LOCK	Repair	168.00 FL	*- FL
21	1		*BONNET IMPACT PROTECTION-CENTER	Serviceable	22.00 FL	*- FL
22	2		*BONNET IMPACT PROTECTION-LH/RH	Serviceable	88.00 FL	*- FL
23	1		*BONNET STRIKER-RH	Repair	41.00 FL	*- FL
24	1		*FRONT FENDER-RH	Bent	629.00 FL	*629.00 FL
25	1		*FRONT FENDER ATTACHMENT PARTS	Serviceable	41.00 FL	*- FL
26	1		*FRONT FENDER BRACE-RH	Repair	96.00 FL	*- FL
27	1		*FRONT FENDER TOP COVER-RH	Serviceable	23.00 FL	*-FL
28	1		*SIGN CAUTION STICKER	Necessary	15.00 FL	*15.00 FL
29	1		*AIR CONDITIONER STICKER	Necessary	17.00 FL	*17.00 FL
30	1		*RADIATOR GRILLE INNER BRACE	Cracked	449.00 FL	*449.00 FL
31	8		*BONNET INSULATOR ATTACHMENTS	Not Necessary	44.00 FS	*-FS
32	8		*SUPPORT PANEL GARNISH ATTACHMENTS	Not Necessary	44.00 FS	*-FS
33	10		*FRONT BUMPER ATTACHMENTS	Necessary	55.00 FS	*55.00 FS
34	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
35	1		*FRONT NUMBER PLATE	Bent	55.00 FS	*45.00 FS
36	10		*WHEEL HOUSING LINER ATTACHMENTS-RH	Not Necessary	45.00 FS	*- FS
37	1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	16,778.00	14,755.00

 Sub Total (\$\$)
 16,778.00
 14,755.00

 - List Item Discount on L Items 5.00/5.00% (\$\$)
 821.25
 732.75

Total Parts (S\$) 15,956.75 14,022.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	500.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	TO REMOVE AND REPLACE RADIATOR ASSY.TO CHECK COOLING SYSTEM FUNCTIONALITY	New	150.00	0.00
4	TO REMOVE AND REPLACE RADIATOR.TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	150.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	660.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
	Gross Labour	2,850.00	1,180.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >