

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010598/AGA3Q2**Date:** 15/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800063385
Claimant Vehicle No :	SDH6699E	Insured Vehicle No :	SDG711Y
Date of Loss:	11/10/2021	Nature of Claim:	TP
		Claim No:	1256511945SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH6699E	Engine No:	27492031424468
Make & Model:	MERCEDES-BENZ E300, 2.0 AMG (A)	Chassis No:	WDD2383482F053999
Reg. Date:	27/06/2018 (Man. Year: 2018)	Odometer:	54181 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,261.68	41,369.73	9,891.95	19.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,550.00	4,860.00	3,690.00	43.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,811.68	46,229.73	13,581.95	22.71
Approved Total (Overridden) (S\$)		36,900.00		
(S\$)	59,811.68	36,900.00	22,911.68	38.31
+ GST 7.00/7.00% (S\$)	4,186.82	2,583.00	1,603.82	38.31
Nett Amount (S\$)	63,998.50	39,483.00	24,515.50	38.31
+ Loss of Use (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		41,190.45		
Global Sum Settlement (S\$)		41,000.00		

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At:

Estimated Period of Repair: 14.0 days

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM
 Inspection Centre
 Singapore 415933

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,688.20 FL	*2,688.20 FL
2	1		*BONNET LOGO	Necessary	90.00 FL	*90.00 FL
3	2		*BONNET HINGE	Bent	261.00 FL	*261.00 FL
4	2		*BONNET DAMPER	Not Necessary	420.40 FL	*- FL
5	1		*BONNET CENTRE LOCK	Damaged	298.00 FL	*298.00 FL
6	1		*BONNET CENTRE LOCK HOOD	Bent	230.50 FL	*230.50 FL
7	2		*BONNET SIDE LOCK	Damaged	641.00 FL	*641.00 FL
8	1		*BONNET SIDE LOCK PANEL	Dented	1,255.60 FL	*1,255.60 FL
9	1		*FRONT BUMPER	Distorted	1,855.30 FL	*1,855.30 FL
10	2		*FRONT BUMPER SIDE RETAINER	Cracked	261.00 FL	*261.00 FL
11	2		*FRONT BUMPER SIDE LOWER BRACKET	Cracked	221.00 FL	*221.00 FL
12	1		*FRONT BUMPER INNER CENTRE FRAME	Cracked	280.20 FL	*280.20 FL
13	1		*FRONT BUMPER LOWER GRILLE	Cracked	320.00 FL	*320.00 FL
14	1		*FRONT BUMPER LOWER GRILLE CHROME	Cracked	450.20 FL	*450.20 FL
15	1		*FRONT BUMPER TOWING COVER	Deformed	80.00 FL	*80.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	742.00 FL	*742.00 FL
17	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	440.40 FL	*- FL
18	2		*FRONT BUMPER REINFORCEMENT HOOK (UPPER)	Bent	220.00 FL	*220.00 FL
19	2		*FRONT BUMPER REINFORCEMENT HOOK (LOWER)	Bent	240.00 FL	*240.00 FL
20	1		*FRONT BUMPER SPONGE	Cracked	230.20 FL	*230.20 FL
21	1		*FRONT BUMPER WEATHERSTRIP SEAL	Not Necessary	166.20 FL	*- FL
22	4		*FRONT BUMPER SENSOR	Damaged (2 PCS ONLY)	1,282.00 FL	*641.00 FL
23	4		*FRONT BUMPER SENSOR RUBBER	Necessary	120.00 FL	*120.00 FL
24	1		*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	160.00 FL	*160.00 FL
25	2		*FRONT HEADLAMP (HID)	Cracked	10,710.40 FL	*6,950.00 FL
26	2		*FRONT HEADLAMP (HID)COVER	Not Necessary	300.00 FL	*- FL
27	1		*FRONT GRILLE INNER RUBBER	Torn	255.30 FL	*255.30 FL
28	2		*FRONT FENDER (ALUMINIUM)	Buckled	1,710.40 FL	*1,710.40 FL
29	1		*FRONT CIRCULATION PUMP PIPE	Snapped	320.20 FL	*320.20 FL
30	1		*SUPPORT PANEL	Cracked	530.20 FL	*530.20 FL
31	1		*AIRCON CONDENSOR	Dented	1,533.20 FL	*1,325.00 FL
32	2		*AIRCON CONDENSOR SIDE GUIDE	Cut	210.40 FL	*210.40 FL
33	2		*RADIATOR TOP HOUSING BRACKET	Damaged	100.00 FL	*100.00 FL
34	1		*RADIATOR TOP HOUSING RUBBER	Not Necessary	288.20 FL	*- FL
35	1		*RADIATOR	Dented	1,055.80 FL	*1,055.80 FL
36	1		*RADIATOR LOWER TEMPERATURE	Not Necessary	1,145.70 FL	*- FL
37	1		*REAR BOOTLID	Distorted	2,533.90 FL	*2,533.90 FL
38	1		*REAR BOOTLID LOGO	Necessary	133.50 FL	*133.50 FL
39	1		*REAR BOOTLID E300	Necessary	92.30 FL	*92.30 FL
40	1		*REAR BOOTLID AMG	Necessary	90.00 FL	*90.00 FL
41	1		*REAR BOOTLID LOGO OPENER	Cracked	335.20 FL	*335.20 FL
42	1		*REAR BOOTLID LOCK	Damaged	420.00 FL	*420.00 FL
43	1		*REAR BOOTLID LOCK CATCH	Bent	120.20 FL	*120.20 FL
44	1		*REAR BOOTLID LOCK CATCH CABLE	Jammed	320.50 FL	*320.50 FL
45	2		*REAR BOOTLID HINGE	Bent	521.00 FL	*521.00 FL
46	2		*REAR BOOTLID HINGE COVER	Cracked	180.00 FL	*180.00 FL
47	2		*REAR BOOTLID LAMP	Cracked	1,160.60 FL	*1,160.60 FL
48	1		*REAR BOOTLID WEATHERSTRIP	Cut	320.20 FL	*320.20 FL
49	1		*REAR BOOTLID INSULATOR	Not Necessary	420.20 FL	*- FL
50	1		*REAR BOOTLID INSULATOR TOP COVER	Cracked	380.50 FL	*380.50 FL
51	1		*REAR BOOTLID AUTO RELEASE SENSOR (TOP)	Not Necessary	210.00 FL	*- FL
52	1		*REAR BOOTLID AUTO RELEASE SENSOR (LOWER)	Not Necessary	20.00 FL	*- FL
53	1		*REAR BOOTLID AUTO RELEASE MOUDLE	Not Necessary	220.20 FL	*- FL
54	1		*REAR BOOTLID AUTO RELEASE HOUSING	Cracked	380.50 FL	*380.50 FL
55	1		*REAR BUMPER	Distorted	1,988.50 FL	*1,988.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	2	*REAR BUMPER SIDE RETAINER	Cracked	261.00 FL	*261.00 FL
57	1	*REAR BUMPER LOWER LIP CHROME	Cracked	420.20 FL	*420.20 FL
58	1	*REAR BUMPER DIFFUSER	Distorted	680.20 FL	*680.20 FL
59	1	*REAR BUMPER DIFFUSER SIDE LH	Cracked	90.00 FL	*90.00 FL
60	1	*REAR REINFORCEMENT BAR	Dented	820.20 FL	*820.20 FL
61	1	*REAR BUMPER TOWING COVER	Deformed	70.50 FL	*70.50 FL
62	2	*REAR BUMPER REFLECTOR	Cracked	311.20 FL	*311.20 FL
63	1	*REAR BUMPER CENTRE BRACKET	Cracked	211.40 FL	*211.40 FL
64	1	*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	211.40 FL	*- FL
65	1	*REVERSE SENSOR (6 PCS)	Damaged (4 PCS ONLY)	1,920.00 FL	*1,040.00 FL
66	6	*REVERSE SENSOR RUBBER	Necessary	153.00 FL	*153.00 FL
67	6	*REVERSE SENSOR HOLDER	Necessary	363.00 FL	*363.00 FL
68	2	*TAIL LAMP	Cracked	1,041.00 FL	*1,041.00 FL
69	2	*TAIL LAMP LOWER BRACKET	Cracked	202.40 FL	*202.40 FL
70	2	*TAIL LAMP COVER RUBBER	Deformed	240.00 FL	*240.00 FL
71	2	*TAIL LAMP PANEL	Dented	841.00 FL	*841.00 FL
72	2	*REAR FENDER INNER TRIM	Torn	1,300.40 FL	*1,300.40 FL
73	1	*END PANEL	Distorted	1,533.20 FL	*1,320.00 FL
74	1	*END PANEL TOP GARNISH	Deformed	288.30 FL	*288.30 FL
75	2	*EXHAUST CHROME TIP	Not Necessary	840.00 FL	*- FL
76	2	*EXHAUST CHROME TIP BRACKET	Cracked	221.00 FL	*221.00 FL
77	1	*REAR FLOOR PANEL TRAY (FIBRE)	Torn	920.20 FL	*920.20 FL
78	1	*REAR FLOOR PANEL TOP BOARD	Deformed	855.30 FL	*855.30 FL
79	1	*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
80	1	*FRONT BUMPER CLIP (SERT)	Necessary	22.00 FS	*22.00 FS
81	1	*FRONT GRILLE BASE	Cracked	800.00 FS	*600.00 FS
82	1	*FRONT GRILLE LOGO	Necessary	120.00 FS	*85.00 FS
83	1	*FRONT GRILLE LOGO BASE	Cracked	160.00 FS	*120.00 FS
84	1	*FRONT GRILLE LOGO CHROME	Cracked	420.00 FS	*350.00 FS
85	1	*COOLANT	Necessary	160.00 FS	*40.00 FS
86	1	*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
87	1	*SET REAR BOOTLID INSULATOR CLIPS	Not Necessary	20.00 FS	*- FS
88	1	*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
89	1	*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
90	1	*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
91	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 56,737.20 45,806.70
- List Item Discount on L Items 10.00/10.00% (\$\$) 5,475.52 4,436.97

Total Parts (\$\$) 51,261.68 41,369.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	1,000.00
3	WIRING CHECK	New	280.00	50.00
4	REFOCUS HEADLAMP BEAM	New	80.00	0.00
5	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE SETTING	New	100.00	60.00
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	180.00	60.00
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	150.00	60.00
8	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	1,200.00
9	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,000.00
10	TUFF COAT	New	250.00	60.00
11	WIRING CHECK	New	120.00	30.00
12	REMOVE AND REFIX REAR BOOTLID MECHANISM	New	140.00	80.00
13	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	50.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	60.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	250.00	150.00
Gross Labour Cost (\$\$)			8,550.00	4,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >