

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 5269Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LAMP LH (CONSISTENT)	BROKEN	652.25	548.40
1	REAR BUMPER (CONSISTENT)	BUCKLED	860.50	780.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	116.10	116.10
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	116.10	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	958.70	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SCRATCHED	76.27	76.27
6	REAR BUMPER CLIPS @\$8.00 (CONSISTENT)	NECESSARY	48.00	48.00
	LESS 25% DISCOUNT		-706.98	-392.19
			2,120.94	1,176.58
1	REVERSE SENSOR -NEW (SN) (CONSISTENT)	SHORTED	280.00	200.00
	LESS 25% DISCOUNT		-70.00	-
			210.00	200.00
	LABOUR			
	SPRAY PAINT ANTI RUST COATING.	NOT NECESSARY	120.00	-
	CHECK & REAIR WIRING.		90.00	20.00
	REMOVE & REFIX REAR BUMPER PARKING SENSOR .		120.00	50.00
	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS.		900.00	500.00
	REPLACE REAR LAMP ,END PANEL ,BUMPER ,WELDING PANEL BEATING AND TEST WATER LEAKING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		900.00	400.00
			2,130.00	970.00
	GRAND TOTAL		4,460.94	2,346.58

RECOMMENDED COST OF REPAIRS		2,346.58

Report Ref No. CC4/ASM21010606/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser