



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Ref: CC4/ASM21010606/Kpa3q2 Date: 10/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 8868A	Veh. Inspected	SLR 5269Y
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03JP0	Excess (\$)	0.00
	Assign From		Assign Date	14/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NKE1657144020	Colour	METALLIC SILVER
	Odometer	96193 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/65 R15	CONTINENTAL	8 mm
	L/H Front Tyre	175/65 R15	CONTINENTAL	8 mm
	R/H Rear Tyre	175/65 R15	CONTINENTAL	8 mm
	L/H Rear Tyre	175/65 R15	CONTINENTAL	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/10/2021	Inspection Date	15/10/2021
	Survey held at	T & B MOTOR REPAIRS SERVICES PTE LTD BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days