2/7/22, 12:00 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21010607/VPA3Q2

Date: 07/02/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210020207

Claimant Vehicle

No: SHC6355B Insured Vehicle No: SMZ8788S

Date of Loss: 14/10/2021 Nature of Claim: TP Claim No: 9657123413SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6355B

Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDEH313275

Reg. Date: 20/01/2015 (Man. Year: 2014) Chassis No: KNAGM414MF5575384

Colour: Silver Odometer: 595294 km

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 206/60 R16 Rear Tyre Size: 206/60 R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,335.00	106.00	1,229.00	92.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,400.00	780.00	620.00	44.29
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,735.00	886.00	1,849.00	67.61
	+ GST 7.00/7.00% (S\$)	191.45	62.02	129.43	67.61
	Nett Amount (S\$)	2,926.45	948.02	1,978.43	67.61
	+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
	+ Car Rental (2.5 x	S\$67.41/day) (S\$)	168.53		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,243.55		
	Global Sur	m Settlement (S\$)	1,200.00		

INSPECTION

Date of Assignment: 14/10/2021

Premier Automotive Services Pte Ltd (HQ)

Date Inspected: 19/10/2021 Inspected At: 23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: CHEW HSIAO TONG

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	531.00 FL	*- FL
2	1		*FRONT BUMPER EMBLEM	Serviceable	44.00 FL	*- FL
3	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Serviceable	32.00 FL	*- FL
4	1		*FRONT BUMPER N/S UPPER BRACKET	Serviceable	16.00 FL	*- FL
5	1		*FRONT BUMPER N/S SUPPORT BRACKET	Serviceable	16.00 FL	*- FL
6	1		*FRONT BUMPER N/S PROTECTOR	Serviceable	51.00 FL	*- FL
7	1		*FRONT N/S WHEEL COVER	Serviceable	116.00 FL	*- FL
8	1		*FRONT N/S FENDER	Repair	384.00 FL	*- FL
9	1		*FRONT N/S FENDER INNER SHIELD	Serviceable	120.00 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
11	1		*FRONT N/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
12	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	28.00 FS	*28.00 FS
13	1		*SUNDRY	Serviceable	50.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,466.00	106.00
			- List Item Discount on L Item	s 10.00/10.00% (S\$)	131.00	0.00
				Total Parts (S\$)	1,335.00	106.00
			Report was unsubmitted during this	print out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO FOCUS AND ADJUST FRONT N/S & O/S HEAD LAMPS	New	60.00	30.00
2	TO CHECK FRONT WHEEL ALIGNMENT	New	80.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC	Γ New	600.00	360.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,FRONT DOOR LH ,SIDE MIRROR LH	New	600.00	360.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	60.00	30.00
	Gross Labour Cost (S\$)		1,400.00	780.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >