

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010608/TPA3Q2**Date:** 30/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070149064
<b>Claimant Vehicle No :</b>	SML3668L	<b>Insured Vehicle No :</b>	SJV7727G
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	6054808049SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML3668L</b>	Engine No:	HIDDEN
Make & Model:	BLUECAR BLUECAR, (A)	Chassis No:	VL4BCEB4RJT003539
Reg. Date:	16/05/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,904.40	6,301.20	4,603.20	42.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,860.00	1,760.00	48.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>14,524.40</b>	<b>8,161.20</b>	<b>6,363.20</b>	<b>43.81</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	14/10/2021		
Date Inspected:	15/10/2021	Inspected At:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315
Estimated Period of Repair:	8.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	1,493.00 F	*1,493.00 F
2	10		*FRONT BUMPER CLIPS (WCP)	Necessary	10.00 F	*10.00 F
3	1		*FRONT REINFORCEMENT (WCP)	*Check	240.00 F	*- F
4	2		*FRONT REINFORCEMENT BRACKET (WCP)	*Check	400.00 F	*- F
5	1		*FRONT BUMPER SPONGE WITH CLIPS (WCP)	Cracked	169.00 F	*169.00 F
6	1		*FRONT SUPPORT PANEL (WCP)	Bent	412.00 F	*412.00 F
7	1		*FRONT BONNET LOCK (WCP)	*Check	96.00 F	*- F
8	1		*FRONT BONNET (WCP)	Bent	1,197.00 F	*1,197.00 F
9	1		*BONNET HINGE LH (WCP)	Repair	125.00 F	*- F
10	1		*BONNET HINGE RH (WCP)	Repair	125.00 F	*- F
11	1		*FRONT RADIATOR AIR GUIDE (WCP)	Deformed	62.00 F	*62.00 F
12	7		*AIR GUIDE CLIP (WCP)	Necessary	7.00 F	*7.00 F
13	1		*AIRCON CONDENSER (WCP)	*Check	527.00 F	*- F
14	1		*RADIATOR (WCP)	*Check	530.00 F	*- F
15	1		*RADIATOR FAN MOTOR WITH COWLING (WCP)	*Check	606.00 F	*- F
16	1		*HEADLAMP FRAME RH (WCP)	Cracked	134.00 F	*134.00 F
17	1		*HEADLAMP FRAME LH (WCP)	Cracked	137.00 F	*137.00 F
18	1		*REAR BUMPER (WCP)	Deformed	1,405.00 F	*1,405.00 F
19	1		*REAR BUMPER REINFORCEMENT (WCP)	*Check	82.00 F	*- F
20	1		*REAR BUMPER REINFORCEMENT BRACKET LH (WCP)	*Check	43.00 F	*- F
21	1		*REAR BUMPER REINFORCEMENT BRACKET RH (WCP)	*Check	43.00 F	*- F
22	1		*REAR BUMPER REFLECTOR RH (WCP)	Not Necessary	126.00 F	*- F
23	1		*REAR BUMPER REFLECTOR LH (WCP)	Cracked	125.00 F	*125.00 F
24	1		*REAR END PANEL (WCP)	Repair	450.00 F	*- F
25	1		*CHARGER AIR INLET (WCP)	*Check	115.00 F	*- F
26	1		*CHARGER AIR INLET GASKET (WCP)	*Check	6.00 F	*- F
27	2		*REAR AIR VENT (BOOT/TRUNK) (WCP)	*Check	92.00 F	*- F
28	2		*REAR NUMBER PLATE LAMP (WCP)	*Check	230.00 F	*- F
29	1		*BONNET STICKER	Necessary	30.00 FS	*30.00 FS
30	2		*NUMBER PLATE WITH CASING	Cracked	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>9,107.00</b>	<b>5,271.00</b>
<b>+ Margin on L,N Items 20.00/20.00% (\$)</b>	1,797.40	1,030.20
<b>Total Parts (\$)</b>	<b>10,904.40</b>	<b>6,301.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	800.00	500.00
2	TO PUTTY AND RESPRAY FRONT BUMPER ,BONNET ,RH FENDER AND AFFECTED AREAS	New	600.00	400.00
3	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	800.00	500.00
4	TO PUTTY AND RESPRAY REAR BUMPER ,REAR END PANEL ,REAR FLOOR PANEL ,REAR RH FENDER AND AFFECTED AREAS	New	600.00	400.00
5	TO APPLY TUFF COATING	New	120.00	30.00
6	TO CHECK WIRING AND UPDATE SYSTEM	New	150.00	30.00
7	REMOVE AND REPLACE AIRCON CONDENSER AND RADIATOR (*Check)	New	150.00	0.00
8	TOP UP AIRCON GAS (R1234) (*Check)	New	400.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,620.00</b>	<b>1,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >