

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21010609/AEA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210005261
<b>Claimant Vehicle No :</b>	SNB5773T	<b>Insured Vehicle No :</b>	SBX8668X
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	3123390267SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNB5773T</b>		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	DEM032946
Reg. Date:	30/08/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF57MA054431
Colour:	White	Odometer:	1600 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,002.00	0.00	15,002.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	2,272.00	2,400.00	51.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>19,674.00</b>	<b>2,272.00</b>	<b>17,402.00</b>	<b>88.45</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,377.18	159.04	1,218.14	88.45
<b>Nett Amount (\$\$)</b>	<b>21,051.18</b>	<b>2,431.04</b>	<b>18,620.14</b>	<b>88.45</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (\$\$)</b>		320.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,753.04</b>		

INSPECTION

Date of Assignment:	15/10/2021		
Date Inspected:	20/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,342.00 FS	*- FS
2	2		*FRONT BUMPER SUCURING STRIP	Not Necessary	71.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	196.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	262.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	63.00 FS	*- FS
6	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
7	1		*FRONT BUMPER AIR GRILLE LH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT BUMPER AIR GRILLE COVER -LH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER LOWER TRIM -CENTER	Not Necessary	114.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,694.00 FS	*- FS
11	1		*FRONT BUMPER FOAM PIECE	Not Necessary	146.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
16	1		*LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
17	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	58.00 FS	*- FS
18	4		*RIVET	Not Necessary	4.00 FS	*- FS
19	2		*FRONT BUMPER PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
20	4		*FRONT BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*HORN -LH	Not Necessary	126.00 FS	*- FS
22	1		*HORN BRACKET-LH	Not Necessary	29.00 FS	*- FS
23	1		*HEADLIGHT -LH	Not Necessary	7,685.00 FS	*- FS
24	1		*HEADLIGHT LEFT CYLINDER -LH	Not Necessary	198.00 FS	*- FS
25	1		*HEADLIGHT LEFT CYLINDER HOSE (NPA)	Not Necessary	0.00 FS	*- FS
26	3		*RADIATOR AIR GUIDE -LH/LOWER LH /UPPER	Not Necessary	64.00 FS	*- FS
27	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
28	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **15,002.00**    **0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS TO REPAIR BONNET .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,672.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >