

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21010617/AVF3N2**Date:** 27/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900109971
Claimant Vehicle No :	SJS4178B	Insured Vehicle No :	SMM6790R
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	1758186019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS4178B	Engine No:	3ZZ4921599
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106152046
Reg. Date:	14/08/2009 (Man. Year: 2009)	Odometer:	128789 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,976.53	2,265.60	2,710.93	54.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,600.00	1,170.00	42.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,746.53	3,865.60	3,880.93	50.10
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	7,746.53	3,100.00	4,646.53	59.98

INSPECTION

Date of Assignment:	15/10/2021	MCS GARAGE (HQ)
Date Inspected:	15/10/2021 Inspected At:	10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE
Estimated Period of Repair:	5.0 days	Singapore 417868

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	561.90 FL	*561.90 FL
2	2		*REAR BUMPER REFLECTORS-L/R	Cracked	83.00 FL	*83.00 FL
3	1		*REAR BUMPER FOAM	Cracked	180.93 FL	*180.93 FL
4	1		*REAR BUMPER BRACKETS-L/R	N/s Damaged	220.50 FL	*110.25 FL
5	2		*REAR BUMPER SIDE RETAINERS-L/R	Necessary	183.00 FL	*90.00 FL
6	2		*REAR BUMPER SIDE BRACKETS-L/R	Not Necessary	179.90 FL	*- FL
7	1		*REAR BOOT LID	Repair	861.90 FL	*- FL
8	1		*REAR BOOT LOGO	Necessary	68.60 FL	*68.60 FL
9	1		*REAR BOOT EMBLEM 1.6	Necessary	52.40 FL	*52.40 FL
10	1		*REAR BOOT EMBLEM COROLLA	Necessary	68.20 FL	*68.20 FL
11	1		*REAR BOOT EMBLEM ALTIS	Necessary	68.20 FL	*68.20 FL
12	2		*REAR BOOT LAMPS-L/R	Not Necessary	423.00 FL	*- FL
13	1		*REAR BOOT INNER LOCK	Not Necessary	260.95 FL	*- FL
14	1		*REAR BOOT LOCK STICKER	Not Necessary	78.85 FL	*- FL
15	1		*REAR BOOT W/STRIP	Not Necessary	169.43 FL	*- FL
16	1		*REAR END PANEL	Dented	780.65 FL	*780.65 FL
17	1		*REAR END PANEL GARNISH	Not Necessary	160.93 FL	*- FL
18	1		*REAR FLOOR BOARD	Not Necessary	380.60 FL	*- FL
19	2		*REAR TAILLAMPS-L/R	Cut	823.00 FL	*650.00 FL
20	2		*REAR TAILLAMP LOWER BRACKETS	Not Necessary	173.10 FL	*- FL
21	2		*REAR TAILLAMP PANELS-L/R	Not Necessary	423.00 FL	*- FL
22	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
23	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,527.04	2,944.13
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,550.51	678.53
Total Parts (\$\$)	4,976.53	2,265.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE,REFIX REAR REVERSE SENSOR	New	80.00	50.00
4	TO RESPRAY UNDERCOATING	New	120.00	60.00
5	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
6	PANEL BEATING,CUT,WELD REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$)			2,770.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >