

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21010620/GTY3E2

Date: 19/11/2021

REFERENCE

Insured/Claimant: BUDGETCARS PTE LTD Policy No: DMCVSN1808581800

Date of Loss: 20/10/2018 Nature of Claim: OD Claim No: SNM18D05019/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH2532C**
Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 1KD2733578
Reg. Date: 20/03/2018 (Man. Year: 2017) Chassis No: KDH2010228569
Colour: Silver Odometer: 0 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	750.00	-750.00	
Nett Amount (S\$)	0.00	-750.00	750.00	

INSPECTION

Date of Assignment: 14/10/2021

Date Inspected: 19/10/2021 Inspected At:

68 Kaki Bukit Avenue 6, #02-04/05, ARK@KB
Repairer: Jin Auto Services Pte Ltd

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$82,000.00
OMV :	\$30,811.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$31,027.00
COE Rebate (2) :	\$29,217.00
Total Rebate (1) + (2) = :	\$29,217.00 (estimated)

The total amount incurred will be Market Value \$82,000.00 minus Total Rebate (estimate) \$29,217.00 = \$52,783.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Nov 2021)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH2532C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >